District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party EOG Resources

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1919836650
District RP	2RP-5530
Facility ID	fAB1919836118
Application ID	pAB1919836440

Release Notification

Responsible Party

OGRID 7377

Contact Name Todd Wells			Contact Telephone (432) 686-3613				
Contact email Todd_Wells@eogresources.com			Incident #	(assigned by OCD) NAB1919836650			
Contact mail 79706	ing address	5509 Champions	Drive Midland, T	Ϋ́X	1		
			Location	of R	Release So	ource	
Latitude 32.2	85530°				Longitude -	-103.786315°	
<u>52.2</u>	03330		(NAD 83 in de	ecimal de	egrees to 5 decim	mal places)	
Site Name Double Tin Horn				Site Type	EOG Water Gathering Line		
Date Release Discovered 6/23/19			API# (if applicable)				
	P		-				
Unit Letter	Section 21	Township 23S	Range 31E	Edd	County Eddy		
N	21	233	31E	Edd	y 		
Surface Owner: State Federal Tribal Private (Name:) Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oil		Volume Release			*	Volume Recovered (bbls)	
Noduced Produced	Water	Volume Released (bbls) 85				Volume Recovered (bbls) 78	
	Is the concentration of dissolved chloride produced water >10,000 mg/l?			e in the	⊠ Yes □ No		
Condensate Volume Released (bbls)				Volume Recovered (bbls)			
Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)			
Other (describe) Volume/Weight Released (provide units))	Volume/Weight Recovered (provide units)			
the field appr The water wa gathering line	oximately 1 as shut off and caused the	00-feet north of North of North Nort	New Mexico Hwy were called to pic we was repaired an	128 in k up th	Eddy County e water insid	EOG water gathering system double tin horn located in y, NM, at GPS coordinates: 32.285530°, -103.786315°. de the tin horns. A valve failure on the poly water to service. Approximately 85 bbls of produced water	

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAB1919836650
District RP	2RP-5530
Facility ID	fAB1919836118
Application ID	pAB1919836440

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release? The release is more than 25 bbls.				
19.15.29.7(A) NMAC?					
⊠ Yes □ No					
	tice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Email notification ke Bratcher NMOCD District II on 6/26/19.				
	Initial Response				
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury				
☐ The source of the rele	ease has been stopped.				
_	s been secured to protect human health and the environment.				
	ve been contained via the use of berms or dikes, absorbent pads, or other containment devices.				
All free liquids and recoverable materials have been removed and managed appropriately.					
If all the actions described	l above have <u>not</u> been undertaken, explain why:				
has begun, please attach a	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and				
	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have				
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws					
and/or regulations.	ta e 111 report does not reneve are operation of responsionity for compliance with any other rederat, state, or local laws				
Printed Name:Todd W	Title: Environmental Specialist				
Signature: Todd	Wells Date: <u>6-28-19</u>				
email:Todd_Wells	@eogresources.com Telephone:(432) 686-3613				
OCD Only					
-	Bustamante Date: 7/17/2019				
Received by: Amalia I	Date:				