

## Venegas, Victoria, EMNRD

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Thursday, June 20, 2019 3:37 PM  
**To:** 'DeAnn Grant'; Bratcher, Mike, EMNRD  
**Cc:** Hamlet, Robert, EMNRD; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell  
**Subject:** RE: (C-141 Initial) Patton 5 Fee #002H Battery (30-015-39815) 06-02-2019

**RE: (C-141 Initial) Patton 5 Fee #002H Battery (30-015-39815) 06-02-2019**

All, The OCD tracking number for this release event is **2RP-5492**.

Thank you,

Victoria Venegas  
EMNRD  
OCD-District II  
811 S First St. Artesia  
NM 88210  
[Victoria.Venegas@state.nm.us](mailto:Victoria.Venegas@state.nm.us)

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

---

**From:** DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Sent:** Monday, June 17, 2019 6:54 AM  
**To:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Cc:** Hamlet, Robert, EMNRD <[Robert.Hamlet@state.nm.us](mailto:Robert.Hamlet@state.nm.us)>; Venegas, Victoria, EMNRD <[Victoria.Venegas@state.nm.us](mailto:Victoria.Venegas@state.nm.us)>; Jennifer Knowlton <[jknowlton@concho.com](mailto:jknowlton@concho.com)>; Ike Tavarez <[itavarez@concho.com](mailto:itavarez@concho.com)>; Robert McNeill <[RMcNeill@concho.com](mailto:RMcNeill@concho.com)>; Sheldon Hitchcock <[SLHitchcock@concho.com](mailto:SLHitchcock@concho.com)>; Dakota Neel <[DNeel2@concho.com](mailto:DNeel2@concho.com)>; Rebecca Haskell <[RHaskell@concho.com](mailto:RHaskell@concho.com)>; DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Subject:** [EXT] (C-141 Initial) Patton 5 Fee #002H Battery (30-015-39815) 06-02-2019

Mr. Bratcher,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume for Falcon Lined facilities. The liquid lost estimate is based on the spill dimensions and estimated depth of fluid in the liner. The spreadsheet will calculate the volume lost into the liner. No gravel was present in this lined facility as it is a Falcon Liner. The unrecovered volume is a residue left behind on the liner and equipment which will be cleaned by pressure wash. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

***DeAnn Grant***

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

