District I 1625 N. French Dr., Hobbs, NM 88240 District III 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1927162165	
District RP	2RP-5631	
Facility ID		
Application ID	pAB1927161527	

WU6L7-190905-C-1410

Release Notification

Responsible Party

Responsible Party Natural Gas Pipeline Co. of America LLC	OGRID 329155
Contact Name Glen Thompson	Contact Telephone (432) 333-5518
Contact email glen_thompson@kindermorgan.com	Incident # (assigned by OCD) NAB1927162165
Contact mailing address 1550 Windway, Odessa, TX 79761	

Location of Release Source

Latitude 32.7895739

Longitude <u>-104.2383265</u> (NAD 83 in decimal degrees to 5 decimal places)

 Site Name **NGPL's Indian Basin Line
 Site Type Natural gas steel transmission pipeline

 **NATURAL GAS PIPELINE INDIAN BASIN LINE
 API# (if applicable) N/A

Unit Letter	Section	Township	Range	County	
L	36	17 South	27 East	Eddy	

Surface Owner: 🛛 State 🗌 Federal 🗌 Tribal 🗌 Private	e (<i>Name</i> : _
-----------------------------------------------------	---------------------

Nature and Volume of Release

Mate	rial(s) Released (Select all that apply and attach calculations or specifi	c justification for the volumes provided below)
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
🗌 Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Mix of condensate &	Original estimate approximately 25 barrels; revised	None
used oil	estimate approximately 70 barrels.	

Cause of Release At approximately 5:52 p.m. MTN a person working in the Loco Hills NM area contacted Natural Gas Pipeline Company of America LLC (NGPL) and reported a pipeline rupture. Pressure drop in NGPL's Indian Basin Line was confirmed and the 20-inch diameter steel natural gas pipeline was shut in. NGPL personnel arrived on-site at 7:35 p.m. MTN and confirmed the rupture. There was no fire or injuries. On-site personnel confirmed that the ground surface was impacted from pipeline liquids in the form of a mist/spray.

Form C-141	State of New Mexico			
			Incident ID	NAB1927162165
Page 2	Oil Conservation Division		District RP	2RP-5631
			Facility ID	
			Application ID	pAB1927161527
Was this a major release as defined by 19.15.29.7(A) NMAC? ⊠ Yes □ No	If YES, for what reason(s) does the responsible part approximately 25 barrels was based on visual obser during evening hours with limited daylight. That es based on visual inspection the during daylight hours	vation from o stimated relea	perations personnel tl	hat arrived on-site
Yes, Glen Thompson spo	otice given to the OCD? By whom? To whom? Who oke with Mike Bratcher from the District 2 Office b vold and left a voicemail detailing the incident on 08/2	by phone on (08/21/19 at 8:23 p.m	
	Initial Response	е		
The responsible	party must undertake the following actions immediately unless they	, could create a s	afety hazard that would re	sult in injury
		1.1.1.1.1.1.1		
 The impacted area ha Released materials ha All free liquids and re 	ease has been stopped. Is been secured to protect human health and the enviro ave been contained via the use of berms or dikes, abso ecoverable materials have been removed and managed d above have <u>not</u> been undertaken, explain why:	orbent pads, o		evices.
has begun, please attach within a lined containmer The top 1 to 2 inches of surface material was colle	IAC the responsible party may commence remediation a narrative of actions to date. If remedial efforts hav at area (see 19.15.29.11(A)(5)(a) NMAC), please attact f affected surface area nearest the pipeline (approxin ected and placed into roll-off bins. NGPL also scrap ither side of the swale for approximately 350 feet an	ve been succe ch all informa mately 100 fe bed the top 2	essfully completed or ition needed for closu eet by 130 feet) was inches of soil from th	r if the release occurred ire evaluation. scraped. That scraped he nearby swale and 15
of 240 feet of 5-inch "	ne trench where the rupture occurred has been excava Sheen Clean Oil Only" boom material was place ng the area if a rain event occurs. NGPL will also dev CD.	ed in 3 separ	rate locations across	s the swale to prevent
regulations all operators are public health or the environ failed to adequately investig	rmation given above is true and complete to the best of my required to report and/or file certain release notifications ar nent. The acceptance of a C-141 report by the OCD does n ate and remediate contamination that pose a threat to groun f a C-141 report does not relieve the operator of responsibil	nd perform corr not relieve the o dwater, surface	ective actions for release perator of liability should water, human health of	ses which may endanger Ild their operations have r the environment. In
Printed Name: <u>G.D. The</u>	Title:	Engineer – E	<u>HS Sr.</u>	
Signature:	Marpso Date:_	09/04/2019		
email: glen_thompson@	<u>kindermorgan.com</u> Telephone:	<u>(432) 333-5</u>	518	

OCD ONLY RECEIVED ONLY: <u>AMALIA BUSTAMANTE</u>

DATE: 9/28/2019