

## Hamlet, Robert, EMNRD

---

**From:** Watson, Debbie <Deborah.Watson@wpxenergy.com>  
**Sent:** Tuesday, June 25, 2019 9:09 AM  
**To:** Bratcher, Mike, EMNRD; Griswold, Jim, EMNRD; Amos, James; Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD  
**Subject:** [EXT] Spill Notification Follow-up email North Brushy Draw Federal 35 #001H

Good Morning,

Here is the updated summary for the release at the header located at the North Brushy Draw Federal 35 #001H:

Well: North Brushy Draw Federal 35 #001H  
API: 30-015-39753  
Surface: B-35-25S-29E  
Lease#: NM-054290  
Well Location: 32.092629, -103.95287  
Spill Location: 32.09314, -103.95284 (header)  
Date of Release: June 23, 2019 @ 5:00 PM  
Volume Released: 130 bbl produced water  
Volume Recovered: 40 bbl produced water

Valve failure at header resulted in release of produced water. Upon discovery, wells were shut-in, and truck called to the location to recover standing fluids. Soil impact includes well pads for the North Brushy Draw Federal 35 #001H and North Brushy Draw Federal 35 #006H. Soils were also impacted off pad near the #1H and #6H locations.

Please contact me with any questions.

Thank you,

Debbie

Deborah Watson  
Environmental Specialist  
5315 Buena Vista Drive | Carlsbad, NM 88220  
office 575.885.7561 | cell 505.386.9693  
[deborah.watson@wpxenergy.com](mailto:deborah.watson@wpxenergy.com)



*If you have received this message in error, please reply to advise the sender of the error and then immediately delete this message. Thank you.*