Venegas, Victoria, EMNRD

From: Laci Luig <lluig@cimarex.com>
Sent: Friday, October 2, 2020 11:43 AM

To: Eads, Cristina, EMNRD; EMNRD-OCD-District1spills; Venegas, Victoria, EMNRD; BLM

SPILL (blm_nm_cfo_spill@blm.gov)

Cc: Gloria Garza

Subject: [EXT] RE: Cimarex Reportable Spill - James 29 Fed Battery - 9.27.2020

Attachments: IMG_9734.JPG; IMG_9735.JPG; IMG_9736.JPG; IMG_9737.JPG; IMG_9738.JPG; IMG_

9739.JPG

Good Afternoon!

The lined containment at the James 29 Federal Battery is ready for inspection. Attached are pictures from our inspection proving the liner is intact.

Incident ID nRM2027247695

Thank you & have a great weekend! Laci

From: Gloria Garza <ggarza@cimarex.com> Sent: Sunday, September 27, 2020 9:15 PM

To: Eads, Cristina, EMNRD <Cristina.Eads@state.nm.us>; emnrd-ocd-district1spills (emnrd-ocd-district1spills@state.nm.us) <emnrd-ocd-district1spills@state.nm.us>; Venegas, Victoria, EMNRD

<Victoria.Venegas@state.nm.us>; BLM SPILL (blm_nm_cfo_spill@blm.gov) <blm_nm_cfo_spill@blm.gov>

Cc: Laci Luig < lluig@cimarex.com>

Subject: Cimarex Reportable Spill - James 29 Fed Battery - 9.27.2020

All,

We had a leak today at the James 29 Federal Battery. We found a water dump on the separator had developed a leak and released 6 barrels of water and 2 barrels of oil onto the lined containment. We were able to recover all fluids.

JAMES 29 FEDERA

CIMAREX ENERGY

[53805] SAND DUN

B-29-23S-32E

330 FNL & 2310 FE

A C-141 will be submitted online.

Thank you,

Gloria Garza 432.234.3204

From: XEC Apps < DONOTREPLY DEVAPPS@cimarex.com>

Sent: Sunday, September 27, 2020 4:00 PM

Subject: New Incident Created

New Incident Created 27788

PDF Report

Incident Type: Spill Sub Type: N/A

Severity Level: Level 1

District: Permian Basin-Northeast

Department: Production

Facility Name: PBNM430-JAMES 29 FED

Reported By: Jaime Sauceda Reported By Phone Number:

Incident Time: 9/27/2020 08:45 AM

Completed By: Charlie Fisher on 09/27/2020

Contractor Involved: No

Operation

Pumper making normal rounds finds a kimray manual water dump washed out

Cause of Spill: Material Failure

Material: Produced Water Spilled: 6 Barrels (bbls) Recovered: 6 Barrels (bbls)

Material: Crude Oil Spilled: 2 Barrels (bbls) Recovered: 2 Barrels (bbls) Was Spill Contained: Yes Is Containment Lined: Yes

Description

Pumper finds kimray water dump cut out and spilling produced water and oil into the containment. Pumper isolated the leak and called a vacuum truck to suck up the spill. Will pressure wash containment and replace the dump ASAP

Causes

Comment

Automated Message Sent By Radar: https://apps.cimarex.com/Radar/usersetup