



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Oil Conservation Division

Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"

07-Apr-04

MERIT ENERGY CO
12222 MERIT DR STE 1500
DALLAS TX 75251-0000

NOTICE OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

FREN OIL COMPANY No.007

30-015-05255-00-00
N-19-17S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result:	F	Repair Due: 7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:
Comments on MIT:	SHUT-IN. Tubing pressure is over max injection pressure.			

TURNER B No.076

30-015-05475-00-00
P-30-17S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI: 1200
Test Reason:	Annual IMIT	Test Result:	F	Repair Due: 7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured			

EAST SHUGART UNIT No.001

30-015-05613-00-00
P-27-18S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result:	F	Repair Due: 7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Tubing	FAIL CAUSE:
Comments on MIT:	Guage on casing valve indicating pressure on tubing annulus.			

EAST SHUGART UNIT No.003**30-015-05683-00-00**

A-34-18S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1200
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Tubing	FAIL CAUSE:	
Comments on MIT:	Guage on casing valve indicating pressure on tubing annulus.				

EAST SHUGART UNIT No.002**30-015-05684-00-00**

B-34-18S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Tubing	FAIL CAUSE:	
Comments on MIT:	Guage on casing valve indicating pressure on tubing annulus.				

EAST SHUGART UNIT No.015**30-015-05687-00-00**

F-34-18S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1300
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Tubing	FAIL CAUSE:	
Comments on MIT:	Continuous water flow out int casing valve.				

EAST SHUGART UNIT No.052**30-015-27946-00-00**

B-35-18S-31E

Test Date:	4/6/2004	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result:	F	Repair Due:	7/10/2004
Test Type:	Bradenhead Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	SHUT-IN. Tubing pressure is over max injection pressure.				

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.