

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised May 08, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30.015.01558</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: <b>Empire Abo Unit 'B'</b>
8. Well No. <b>40</b>
9. OGRID Number <b>000778</b>
10. Pool name or Wildcat <b>Empire Abo</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	RECEIVED FEB 12 2004 OCD-ARTESIA
2. Name of Operator <b>BP America Production Company</b>	
3. Address of Operator <b>P.O. Box 1089 Emice NM 88231</b>	
4. Well Location	

Unit Letter **H** : **2310** feet from the **N** line and **660** feet from the **E** line  
Section **26** Township **17S** Range **28E** NMPM County **EDDY**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

09.25.78: Records indicate 5-1/2" csg was circ to surf w/2910 sxs cmt to shut off water flow. Well has 4 sets of squeeze holes and 5 CR's still in the hole.

10.14.92: WL Srvey indicates TOC inside 5-1/2" csg @ 97'

07.2002: Discussed well history with Van Barton, OCD. Permission was granted to finish plugging the well by dumping a cmt plug on top of the 5-1/2" csg.

08.2002: Dig out and removed tbg head.  
Dump cmt plug on top of 5-1/2" csg to surf.  
Cut off wellhead & anchors 3' BGL. Install dry hole marker. Well P&A'd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Staff Support DATE 02.10.04

Type or print name Kellie D. Murrish


Telephone No. 505.394.1649

(This space for State use)

APPROVED BY [Signature] TITLE Wild Sup DATE JUN 30 2004  
Conditions of approval, if any:

# Empire Abo Unit 'B' 40

Potential  
Perforation  
Zones



- KB at 3675' above sea level (Used as the Datum)
- Well is currently shut in
- Top of Cement at surface
- 8-5/8" - 28# casing set at 738' (11' hole)
- 4 Squeeze holes at 1080', Squeezed off w/ CR at 1002'
- 4 Squeeze holes at 1380', Squeezed off w/ CR at 1315'
- 4 Squeeze holes at 1758', Squeezed off w/ CR at 1697'
  
- 4 Squeeze holes at 4900', Squeezed off w/ CR at 4769'
  
- Top of Abo at 6202'
  
- Perforations 6217' - 6227' Closed off w/ CR
  
- Perforations 6270' - 6280' Closed off w/ CR
  
- CBP set at 6300' w/ 4 sx cement on top
- Perforations 6298' - 6318' Closed off w/ CBP
- Junk pkr left in hole at 6315'
  
- PBTD at 6347'
- 5-1/2" - 15.5# casing set at 6383' (7 7/8" hole)



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

16 February 2004

BP America Production  
P.O. Box 1089  
Eunice, New Mexico 88231

RECEIVED

JUN 23 2004

OCD-ARTESIA

Form C-103 Report of Plugging for your Empire Abo Unit "B" # 40 H-26-17-28 API 30-015-01558  
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to  
be cleared to comply with OCD rules and regulations. Please check each item in the space provided to  
indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in  
concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name,  
well number and location including quarter/quarter section or unit letter, section, township, range and API  
well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been  
cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☐ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been  
leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for  
plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and  
returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and  
approval

Name

Title

Van Barton  
Field Rep. II