Oil Cons. UNITED STATES DEPARTMENT OF THE INTERIOR N.M. DIV-Dist. 2

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

Date

BUREAU OF LAND MANAGEME 1301 W. Grand Avenue Lease Serial No. SUNDRY NOTICES AND REPORTS ON AMBOSIA. NM 88210 NM 02427 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on reverse side 1. Type of Well West Square Lake Unit #73884U4270 15161718192 8. Well Name and No. Oil Well Gas Well Other 2. Name of Operator Tract 15 Well 7 9. API Well No. J. Cleo Thompson 3b. Phone No. (include aron gode) 30-015-03994 3a. Address 10. Field and Pool, or Exploratory Area P.O. Box 237 Loco Hills, NM 88255 Grayburg San Andreas 4. Location of Well (Footage, Sec., T, R., M., or Survey Description) OCD - ARTESIA 11. County or Parish, State Unit Letter C of Sec. 34 T16S, R30E NMP 660 N - 1981) ii Eddy, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Deepen \mathbf{M} Production (Start/Resume) Acidize Notice of Intent Well Integrity Fracture Treat Reclamation Alter Casing Casing Repair **New Construction** Recomplete ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1. Rig up on 2/22/01. 2. Pull rods and tubing. 3. Pick up 6 3/4 mill, 6 - 3 1/2 D.C. G.I.H. Mill & Clean out well to T.D. & pump 50 sx cap plug. 4. Pick up 4 1/2 float shoe G.I.H. 62 jts 4 1/2 csg. Shoe set @ 2792' Tie onto 4 1/2 csg. Pump 300 sx cmt. to surface & tie onto 7" 5. Pick 3 7/8 bit 6 - 3 1/2 drill collars G.I.H. drill out plug and drill out dwn to T.D. 3133' C.O.H. lay dwn tools. 6. Run Production Equipment. ACCEPTED FOR RECORD 5/31/01 Put on Production 2790' 4 1/2 10.60 J-55 FEB 1 2 2003 ALEXIS C. SWOBODA PETROLEUM ENGINEER 14. 1 hereby certify that the foregoing is true and correct Name (PrintedlTyped) Title **Production Foreman** Amador Pando Jr Signature 6/05/01 THIS SPACE OR FEDERAL OR STATE OF HEELISE Name Approved by (Signature)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Printed/Typed) Office