

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-63598
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-2005
7. Lease Name or Unit Agreement Name Comanche State
8. Well Number 1
9. OGRID Number 185217
10. Pool name or Wildcat WC - San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	RECEIVED DEC 16 2003 OCD-ARTESIA
2. Name of Operator Fred F. Pool, III	
3. Address of Operator P.O. Box 132 Roswell, NM 88202	
4. Well Location Unit Letter <u>M</u> : <u>330</u> feet from the <u>South</u> line and <u>990</u> feet from the <u>West</u> line Section <u>13</u> Township <u>10S</u> Range <u>26E</u> NMPM County <u>Chaves</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3747 GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Drilled 7 7/8" hole from 405' to 1861'. Ran compensated neutron w/ GR & DLL. Plugged well as follows in accordance w/directions from Mr. Van Barton of NMOCD. Spot 1st plug from 1861' to 1761' (30 sx C neat). Spot 2nd plug from 640' to 540' (30 sx C neat). Spot 3rd plug across shoe of surface pipe from 448' to 210' (75 sx C w/2% CaCl) WOC 2 hours & tagged @ 210'. Spotted last plug from 60' to surface. Installed Dry Hole Marker.

Well was plugged on 11/22/03.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Fred F. Pool, III TITLE Operator DATE 12/15/03

Type or print name Fred F. Pool, III E-mail address: spool@dfn.com Telephone No. 623-4667
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE AUG 6 2004
Conditions of approval, if any:



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

8-3-04
OK to release
/s.

16 December 2003

Fred F. Pool, III
P. O. Box 132
Roswell, New Mexico 88202

RECEIVED

JUL 21 2004

OCD-ARTESIA


Form C-103 Report of Plugging for your Comanche State # 1 M-13-10-26 API 30-005-63598
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.


Name

OPERATOR
Title


Van Barton
Field Rep. II