## State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised May 08, 2003

WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30.015.22823 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Empire Abo Unit "G" DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well No. RECEIVED 1. Type of Well: Oil Well X Gas Well Other DEC - 8 2004 9. OGRID Number 2. Name of Operator 000778 BP America Production Company **OCU:ARTESIA** 3. Address of Operator 10. Pool name or Wildcat P.O. Box 1089 Eunice NM 88231 Empire Abo 4. Well Location 2400 300 feet from the line and feet from the line Unit Letter \_\_\_ **NMPM** County Section Township 28E Rddv 17S Range 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3670.5' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT MULTIPLE** CASING TEST AND PULL OR ALTER CASING **CEMENT JOB** COMPLETION  $\mathbf{x}$ OTHER: OTHER: TA & MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. TD: 6350' PBD: 5936' CTBP W/35' CMT, CTBP @ 6011', CTCR @ 6100', PKR SHELL @ 6137' PERFS: 5966-6288' 09.02.04: MIRUPU. NDWH. NUBOP. TIH W/BIT & SCRAPER. PU & TEST IN HOLE W/2-3/8" TBG. TEST TO 500# PSI FOR 30 MINS. HELD OK. PREP TO SWAB. 09.07.04: SWAB FL DOWN. PREP TO PERF. 09.08.04: RUWL & PERF WELL W/2 JSPF FROM 5966-76'. 21 HOLES TOTAL. RIH W/ PKR TESTING

TBG IN HOLE. SET PKR @ 5868'.

09.09.04: RU & PMP 1000 GALS 15% HCL DRPPING 30 BALL SEALERS. SWAB BACK.

09.14.04: RU & SET CIBP @ 5936'. DUMP 35' CMT ON TOP OF CIBP. RIH W/TBG & DISPLACE HOLE TEST TO 560# PSI FOR 30 MINS. CHART ATTACHED. W/PKR FLUID.

09.16.04: NDBOP. W/1 JT. 2-3/8" TBG. RDPU. WELL TA'D. NUWH.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE. Scheduler 12.06.04

Type or print name Kellie D.

Telephone No. 505.394.1649

(This space for State use)

APPROVED BY Conditions of approval, if any:

DATE

