

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Oil Cons.  
N.M. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pogo Producing Company

3. Address and Telephone No.

P. O. Box 10340, Midland, TX 79702-7340 (915) 685-8100

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1980' FWL, Section 25, T22S, R31E

5. Lease Designation and Serial No.

NM-25365

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Neff Federal #1

9. API Well No.

30-015-25301

10. Field and Pool, or Exploratory Area

Livingston Ridge Delaware

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Pogo Producing Company plans to P&A the above captioned well.

1. Set a CIBP @ 7260'. Spot 40 sx cmt on top. Spot a 40 sx cmt plug 6900'-6800'.
2. Circ hole w/ P&A mud.
3. Cut 7-5/8" csg @ ±6020'.
4. Spot 70 sx cmt plug inside & outside stub. TAG
5. Spot 100 sx cmt plug 4580'-4480'. TAG
6. Spot 60 sx cmt plug ~~3200'-2100'~~ 2100'-2300' TOP SALADO @ 2326' PER COMP RPT 4/19/86
7. ~~Spot 60 sx cmt plug 1500'-1400'. NOT NEEDED~~
8. Spot 60 sx cmt plug 850'-750'. TAG
9. Spot 10 sx cmt surface plug. Install P&A marker. 50' SURFACE PLUG

14. I hereby certify that the foregoing is true and correct

Signed

*Cathy Tomber*

Title Sr. Operation Tech

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

APPROVED

APR 29 2003  
Date 04/24/03

Date LES BABYAK  
PETROLEUM ENGINEER