

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/5/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: OWL 20504 JV-P #005	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35435
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 18	Township 26S	Range 27E	Feet from the 2310	North/South Line South	Feet from the 2310	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.0414886 Longitude - 104.2282181

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 100 bbls Oil ; 510 bbls PW	Volume Recovered: 90 bbls Oil ; 500 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 6/24/2015 11:00 am	Date and Hour of Discovery: 6/24/2015 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: Fri 6/26/2015 2:33 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a tank overflow due to an issue with the transducer valves. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release over ran the lined bermed area but remained on location. An initial scrape was completed. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Lupe Carrasco		Approved by Environmental Specialist: Denied 8/5/2015 HMP	
Title: Environmental Coordinator		Approval Date:	Expiration Date:
E-mail Address: gcarrasco@concho.com		Conditions of Approval:	
Date: August 3, 2015 Phone: 575-748-6940		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3104