

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/19/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Bose Ikard 4 State Com #18H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-42404
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 4	Township 17S	Range 29E	Feet from the 330'	North/South Line South	Feet from the 330'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude32.857365757189 **Longitude**-104.087356260491

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 155 bbls PW	Volume Recovered: 150 bbls PW
Source of Release: Poly Flowline	Date and Hour of Occurrence: 3/2/2015 1:30 pm	Date and Hour of Discovery: 3/2/2015 1:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – NMOCD	
By Whom? Garrett Merket	Date and Hour: 3/2/2015 9:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by when a weld on a ploy flow failed. Vacuum trucks were dispatched to recover all standing fluid and the poly line repaired.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in the pasture and is approximately 100' x 120' in size. This release was addressed under the guidance of NMOCD per the approved workplan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 8/21/2015	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: August 18, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-2913