

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV PC #012H; 2RP#3430	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner:	API No. 30-015-40126
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter O	Section 16	Township 24S	Range 30E	Feet from the 50	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.123948° Longitude: W 103.878668°

**NATURE OF RELEASE**

Type of Release: crude oil	Volume of Release: 18.5 bbls	Volume Recovered: 16.5 bbls
Source of Release: failed 45 elbow connection	Date and Hour of Occurrence: 12/2/15 @ 10 am	Date and Hour of Discovery: 12/2/15 @ 10:35 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable


**Describe Cause of Problem and Remedial Action Taken.\***

BOPCO EHS was notified of a release that occurred when the threads of a 45 elbow connection failed; the majority of the fluid was contained inside the lined firewall containment, However a small amount of oil was sprayed to the well pad. A vacuum truck was called to the location.

**Describe Area Affected and Cleanup Action Taken.\***

The majority of the fluid was contained inside the lined firewall containment. However a small amount of oil was sprayed to the well pad. A vacuum truck was called to the location and recovered 15 barrels of oil from the lined containment and 1.5 barrels of oil from the ground surface. Samples were collected, and based on laboratory analytical data and NMOCD approval: the contaminated soil was excavated and hauled to a state approved disposal facility, and the excavation backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Bradley Blevins	Approved by Environmental Specialist:		
Title: Assistant Remediation Foreman	Approval Date: 1/22/2016	Expiration Date: N/A	
E-mail Address: bblevins@basspet.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>	
Date: 1-8-2016	Phone: 432-214-3704	FINAL	

\* Attach Additional Sheets If Necessary

2RP-3430