State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

**Release Notification and Corrective Action** 

Received 1/26/2016 NMOCD Artesia

> Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

						OPERA	FOR	Ir	🗌 Initial Report 🛛 Final Report		
Name of Company ConocoPhillips						Contact					
Address 1410 N West County Road						Telephone No.					
Facility Name James E Federal Upper Battery						Facility Type Battery					
Surface Owner BLM Mineral Owner						Federal Government			Lease No. 0479142		
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Lin	e County		
E	12	12S	30E						Eddy		
Latitude 32.40849 Longitude 103.9480											
NATURE OF RELEASE											
Type of Rele	ease Hydr	ocarbon produ	iced wate	r & oil					ume Recovered 16bbls oil/4bbls		
						oil/5bbls of produced water water					
Source of Release Overflow/Tank						Date and Hour of Occurrence Date and Hour of Discovery 12/29/12 10:10 am MST 10:45 am MST			scovery 12-29-12		
Was Immediate Notice Given?						If YES, To Whom?					
			Yes 🗵	No 🗌 Not Re	quired						
By Whom?						Date and Hour					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
Yes 🖾 No											
If a Watercou	urse was Im	pacted, Descr	ibe Fully.	k		<b></b>					
Describe Cause of Problem and Remedial Action Taken.*□Air line freeze up causing production equipment to fail/overflowing separator into blow down tank. Isolated by operator trucks called in to pick up fluids.											
Describe Area Affected and Cleanup Action Taken.* CoP scraped up the wet material in the pasture and disposed of the soil at a NMOCD											
										30 ft, 40- mil liner	
				All excavated so							
disposal. A total of 180 cubic yards of top soil and 35 yards of base course were imported to the site to serve as backfill. A 5 point											
composite of the imported soil was taken to a commercial laboratory for analysis and returned a chloride value 80 mg/kg. The site was backfilled with the imported top soil and contoured to the surrounding location. On January 29 <sup>th</sup> , 2015, the disturbed area was seeded with BLM #2.											
	fy that the i	nformation gi	ven above	is true and comple	ete to th	e best of my	knowledge and u	nderstand that p	ursuant to NM	fOCD rules and	
				nd/or file certain re							
				e of a C-141 repoi							
										ater, human health	
federal, state,				tance of a C-141 r	eport ac	bes not renev	e the operator of i	responsibility to	r compliance v	with any other	
Touorai, state,						OIL CONSERVATION DIVISION					
Signature:	K	h- 2	Ľ			<u>OIE CONSERVATION DIVISION</u>					
Printed Name	. Rob		535			Approved by Environmental Specialist:					
Title: SEA	m Su	rface P	rojec	ts Supervis	sor 1	Approval Date: 1/26/2016 Expiration Date:			n Date: N	I/A	
E-mail Addre			Dobbs	@ Cop.co	<u>n</u> o	Conditions of	Approval: N/A	A	Attached	1	
Date:	17/1	,	Phone:	281-455-9	1821	FINAL					

\* Attach Additional Sheets If Necessary

2RP-1509