

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1601540259

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-JV-CVX-BS #028H; 2RP #3496	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-42393	

LOCATION OF RELEASE

Unit Letter A	Section 23	Township 24S	Range 30E	Feet from the 590	North/South Line North	Feet from the 1060	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.20902° Longitude: W 103.84621°

NATURE OF RELEASE

Type of Release: crude oil	Volume of Release: 14 bbls	Volume Recovered: 10 bbls
Source of Release: stuffing box	Date and Hour of Occurrence: 1/11/16 @ 8 am	Date and Hour of Discovery: 1/11/16 @ 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* BOPCO pumper reported that the packing in the stuffing box failed. A vacuum truck was called to the location and was able to recover 10 barrels of oil from around the wellhead.		
Describe Area Affected and Cleanup Action Taken.* The majority of the fluid collected around the wellhead, a vacuum truck was called to the location and was able to recover 10 barrels of oil. The release area was remediated in conjunction with one other release; 2RP-3516. Contaminated soil was excavated and hauled to a state approved disposal facility and samples were collected. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: <i>MBratcher</i>	
Printed Name: Bradley Blevins	Approval Date: 3/7/16	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval: N/A	
E-mail Address: bblevins@basspet.com	FINAL	Attached <input type="checkbox"/>
Date: 3-2-16	Phone: 432-214-3704	

* Attach Additional Sheets If Necessary

2RP-3496