

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nMLB1216446153

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Energy	Contact: Aaron Hickert
Address: 2130 W Bender, Hobbs, NM 88240	Telephone No. 432-363-9496
Facility Name: Skelly A Tank Battery / Skelly Unit #128	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-22262	

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 17S	Range 31E	Feet from the 450	North/South Line North	Feet from 450	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	------------------	------------------------	----------------

Latitude: 32.8261140037943 Longitude: -103.850406737217

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30 gal	Volume Recovered: 0
Source of Release: Compressor	Date and Hour of Occurrence 05/27/2012 2:00 PM	Date and Hour of Discovery 05/27/2012 2:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher – NMOCD, Terry Gregston – BLM	
By Whom? Joe Hernandez	Date and Hour: 05/30/2012 1:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Fluid on vent line high pressure on vessel because Frontier gas plant lost electricity, compressors down and maintenance on compressor caused high pressure – 75 psi – had to vent production separator. Fluid blowing out vent with 25 – 30 mph wind, sprayed 25' x 60' on grass and topsoil.

Describe Area Affected and Cleanup Action Taken.

The impacted soils were scraped and properly disposed of at a NMOCD approved facility. The excavation was backfilled with clean, imported caliche to ground surface and contoured to the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Aaron Hickert	Approved by Environmental Specialist: 	
Title: Sr EH&S Representative	Approval Date: 2/3/17	Expiration Date: 2/3/17
E-mail Address: ahickert@linenergy.com	Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>
Date: 01/31/2017 Phone: 432-363-9496		

* Attach Additional Sheets If Necessary

2RP-1161