

District I
1625 N. French Dr., Hobbs, NM 88240

District II
811 S. First St., Artesia, NM 88210

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1625749235

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-685-4304
Facility Name: CCAP State Com #002	Facility Type: Tank Battery

Surface Owner: Fee	Mineral Owner:	API No. 30-015-31567
--------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	16	22S	27E	990	South	1488	East	Eddy County, NM

Latitude N 32.38799°

Longitude W 104.19135°

NATURE OF RELEASE

Type of Release: Oil & Produced water	Volume of Release: 5 bbls oil, 50 bbls produced water	Volume Recovered: 5 bbls oil, 50 bbls produced water
Source of Release: Oil Tank	Date and Hour of Occurrence 09/06/2016 @ 12:00 pm	Date and Hour of Discovery 09/06/2016 @ 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NMOCD, Amber Groves- NMSLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 09/07/2016 @ 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole in the middle of the oil tank caused by corrosion. Production fluid was moved to another tank. A vacuum truck recovered all free-standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck removed all the free standing fluids. The site was delineated and the results were used to compose a remediation plan. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 02/09/2017.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs		Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 4/11/2017	Expiration Date: N/A	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 4/4/17	Phone: (432) 683-7443		
FINAL			

* Attach Additional Sheets If Necessary

2RP-3881