

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

pAB1801849559

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Marathon Oil Permian LLC	Contact: Jason Wardell
Address: 5555 San Felipe St., Houston, TX 77056	Telephone No.: 575-297-0682
Facility Name: Red Light 27 34 State COM 2H	Facility Type: Oil Well
Surface Owner: State	Mineral Owner: State
API No.: 30-015-43917	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	23S	26E	150	FNL	990	FWL	Eddy

Latitude 32.28208193 Longitude -104.28644227 NAD83

### NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: .14 bbls	Volume Recovered: 0
Source of Release: Flare	Date and Hour of Occurrence: 01/08/2018 – 1130 HRS	Date and Hour of Discovery: 01/08/2018 – 1130 HRS
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Email to Crystal Weaver and Mike Bratcher, Email to Amber Groves	
By Whom? Jason Wardell	Date and Hour: 01/08/2018 1544 HRS	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Crew was onsite preparing to install hi level shut downs on the inlet separator. The crew did not follow procedure and closed a valve before shutting in the well. This resulted in sending fluid through the gas line to the flare. The fluid ignited causing a small fire below the flare which was extinguished by the crew onsite. During the event, approximately .14 bbls spilled onto location in the form of a fine mist.		
Describe Area Affected and Cleanup Action Taken.* .14 bbls of oil in the form of a fine mist impacted the caliche directly north of the flare and remained on location. The top layer of caliche has been removed and disposed of properly at R360 and will be replaced with clean material.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Callie Karrigan</i>		OIL CONSERVATION DIVISION
Printed Name: Callie Karrigan		
Title: HES Professional	Approval Date: 07/25/18	Expiration Date: N/A
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 02/26/2018	Phone: 575-297-0956	

\* Attach Additional Sheets If Necessary

FINAL

2RP-4570

