

Received 7/25/2018

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1618838854

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Wade Dittrich
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 390-2828
Facility Name	Government NBFDD Battery, East Oil Tank	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	Eddy County, NM
---------------	-----	---------------	--	---------	-----------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	20S	28E					Eddy County, NM

Latitude N 32.58240° Longitude W-104.15550° NAD83

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	19 bbls
Source of Release	Hole in the bottom of the tank	Date and Hour of Occurrence	Date and Hour of Discovery		
		06/21/2016			
Was Immediate Notice Given?		If YES, To Whom?			
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required		Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM			
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	06/21/2016 @ 4:12 pm		
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A hole in the bottom of the tank cause 20 bbls of produced water to leak onto the lined facility. The fluids were recovered and the tank was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 20' on location inside the lined containment. Remediation was completed by removing the impacted soil covering the liner and replacing it with clean material. The liner integrity was inspected and verified to be intact. Picture attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Wade Dittrich		Approved by Environmental Specialist: 	
Title: Environmental Specialist		Approval Date: 7/31/2018	Expiration Date: N/A
E-mail Address: Wade_Dittrich@oxy.com		Conditions of Approval: Like approval BLM	
Date: 7-24-18 Phone: (575) 390-2828		FINAL	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3762