

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCD Rec'd:08/03/18

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR



Initial Report

Final Report

Name of Company Marathon Oil Permian LLC O: 372098	Contact Callie Karrigan	
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)	
Facility Name: Sterling State 23 27 20 TB 004H	Facility Type Oil and gas production facilities	
Surface: Owner: state	Mineral: Owner: state	API No. : 30-015-42731

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	23S	27E	603	South	1462	east	Eddy

Latitude 32.28465704.Longitude -104.20827171

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 10 bbls	Volume Recovered: 9.8 bbls
Source of Release: produced water truck hauler	Date and Hour of Occurrence 7/21/2018 4:00 pm	Date and Hour of Discovery 7/21/2018 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Eddy County – Mike Bratcher and Ryan Mann	
By Whom? Callie Karrigan	Date and Hour 7/22/2018 9:14 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* Not applicable.		
Describe Cause of Problem and Remedial Action Taken.* A produced water hauler had been on location to haul produced water from location for disposal. The hauler completed the load but failed to disconnect from the load line before leaving location. Approximately 10 bbls was released inside lined containment from the load line.		
Describe Area Affected and Cleanup Action Taken.* Less than an inch of standing fluids affected the majority of lined containment for the tanks and facility. A vac truck was dispatched to recover standing fluids. Residual fluids were then recovered with absorbent material and the liner was pressure washed. The liner was inspected and assessed for integrity and inspection yielded that it maintained complete integrity.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Callie Karrigan Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Callie Karrigan	Approved by Environmental Specialist: Maria Pruett	
Title: HES Environmental Professional	Approval Date:08/11/18	Expiration Date:N/A
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval: Confirm location and add pictures of liner for closure.	Attached <input type="checkbox"/> 2RP-4918
Date: 8/3/18 Phone: 405-202-1028(cell) 575-297-0956 (office)		

* Attach Additional Sheets If Necessary

A#: pMAP1822350496

I#: nMAP1822350673

Post release



After Clean-up