Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

0	pe	ra	to	r
~	$\mu \nu$	ıu	10	

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No-

SUNDRY NOTICES AND REPORTS ON WELLS				NMNM28636				
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well Gas Well Goth	ıer				8. Well Name and No. FEDERAL BL 1			
Oil Well Gas Well Other 2. Name of Operator Contact: HOWIE LUCAS CHEVRON USA INCORPORATED E-Mail: howie.lucas@chevron.com				9. API Well No. 30-015-23782-00-S1				
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706 3b. Phone No. (inc Ph: 832-588-40					10. Field and Pool or Exploratory Area ROBINA DRAW			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish, State			
Sec 17 T23S R24E NWNE					EDDY COUNTY	, NM		
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE	, REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION			TYPE OI	FACTION				
□ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off		
	Alter Casing	☐ Hydra	aulic Fracturing	Reclam	nation	■ Well Integrity		
Subsequent Report	☐ Casing Repair	□ New	Construction	Recom	plete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☑ Plug □ Plug	and Abandon Tempor		orarily Abandon			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for final 12/02/19 MIRU pulling unit. 12/03/19 Killed well, removed 12/04/19 N/U BOPE and pull to 12/05/19 Set CIBP @ 3614', polymer 12/06/19 Pump MLF, pump 25/12/07/19 Tag TOC @ 7522'. Final Final Pump Tag TOC @ 3821'. Eight 12/09/19 Tag TOC @ 3821'. Eight 12/10/19 Establish injection rag 2483?, 2460?, 2435?, and	wellhead. wellhead. tubing. sressure test casing success X CL H cmt @ 3614'-8- ump 25 sx CL H cmt @ 25stablished injection rate.	sults in a multiple led only after all re essfully t/ 1,00 415'. Pump 25 6360'-6162'. P	opsi for 15 min sx CL H cmt @ erforate casing x C cmt @ 382	utes. 2.7750'-755' at 3845?. \$	RECLAM 2'. Squeeze_60 OC & Tag	0-4 must be file	ed once r has	RE
14. I hereby certify that the foregoing is Com Name (Printed/Typed) HOWIE LU	# Electronic Submission For CHEVRON I mitted to AFMSS for proce			the Carls bat 1 12/16/2 119		R RECO	RD	
Signature (Electronic S	Submission)		Date 12/16/2	019	DEC 18	2019		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE	MICEL VILLER	LIE		
Approved By			Title		BUREAU OF LANDIN CARLSBAD FIEL	MANAGEMEN D OFFICE		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office								
States any false, fictitious or fraudulent				d willfully to n	nake to any department or	agency of the	United	

Additional data for EC transaction #495969 that would not fit on the form

32. Additional remarks, continued

2410? with no injection rate.

12/11/19 Pump 50 sx C cmt @ 2552'-2058'. Tag @ 2323'. Perforate at 1637? and 1712?, no injection rate. Pump 50 sx C cmt @ 1762'-1263'.

12/12/19 Tag TOC @ 1497'. Perforate at 453?, establish circulation

(Rext page) (next page)

C-001 C 11110 J (June 2015)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

5.	Lease Serial No.
	NMNM28636

6. If Indian, Allottee or Tribe Name

OMB No. 1004-0137

Expires: January 31, 2018


SUNDRY NOTICES AND REPORTS ON WELLS					
Do not use this form for proposals to drill or to re-enter an					

abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well								
Oil Well X Gas Well Other				8. Well Name and No. Federal BL 1				
2. Name of Operator	Contact: Howie				9. API Well No.			
Chevron USA Incorporated 3a. Address	E-Mail: howie.lu	cas@chevron. b. Phone No. <i>(in</i>		(a)	30-015-23782 10. Field and Pool or Exploratory Area			
6301 Deauville Blvd., Midland, TX		Ph: 832-588-40		<i>e)</i>				
4. Location of Well (Footage, Sec., T., I		11. 002-000-40			Robina Draw 11. Country or Parish,	State		
Sec 17 T23S R24E NWNE	, , , , , , , , , , , , , , , , , , , ,				Eddy County, NM			
***	CK THE APPROPRIATE BOX	K(ES) TO INDIC	ATE NATUR	E OF NOTIO				
TYPE OF SUBMISSION			TY	'PE OF AC'	ΓΙΟΝ			
Notice of Intent	Acidize Alter Casing	Deepen Hydrau	lic Fracturing	Production (Start/Resume) Water Shut-Off				
X Subsequent Report	Casing Repair		onstruction	etion Recomplete		Other		
	Change Plans	X Plug an			porarily Abandon			
Final Abandonment Notice 13. Describe Proposed or Completed O	Convert to Injection	Plug Ba			er Disposal			
the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) 12/02/19 MIRU pulling unit. 12/03/19 Killed well, removed wellhead. 12/04/19 N/U BOPE and pull tubing. 12/05/19 Set CIBP @ 8614', pressure test casing successfully t/ 1,000 psi for 15 minutes. 12/06/19 Pump MLF, pump 25 sx CL H cmt @ 8614'-8415'. Pump 25 sx CL H cmt @ 7750'-7552'. 12/07/19 Tag TOC @ 7522'. Pump 25 sx CL H cmt @ 6360'-6162'. Perforate casing at 3845'. Squeeze 60 sx C cmt @ 3842'-3249'. 12/09/19 Tag TOC @ 3821'. Established injection rate. Squeeze 60 sx C cmt @ 3821'-3228'. WOC & Tag @ 3806'. 12/10/19 Establish injection rate. Squeeze 60 sx C cmt @ 3806'-3213'. Tag TOC @ 3231'. Perforate at 2483', 2460', 2435', and 2410' with no injection rate. 12/11/19 Pump 50 sx C cmt @ 2552'-2058'. Tag @ 2323'. Perforate at 1637' and 1712', no injection rate. Pump 50 sx C cmt @ 1762'-1263'. 12/12/19 Tag TOC @ 1497'. Perforate at 453', establish circulation through surface casing. Squeeze/circulate 145.sx.C.cmt to surface through all casing strings. RDMO, Well P&A'd.								
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)								
Howie Lucas E-ma	il address: howie.lucas@ch	evron.com 7	itle Well A	bandonme	ent Engineer, Attorne	y in Fact		
Signature Date 12/13/19								
THE SPACE FOR FEDERAL OR STATE OFICE USE								
Approved by								
			Title			Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			01.		·			

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)





BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612