District I 1625 N. French Dr , Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

\* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources JUL 09 2012

RECEIVED

Form C-141 Revised October 10, 2003

NMOCD ARTESIA riate District Office in accordance with 19.15.29 NMAC

2RA-1200

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

	Release Notification and Corrective Action												
nMLB/2/	92548	70			<b>OPERA</b>	FOR	$\boxtimes$	Initial Repo	rt	Final I	Report		
		inn Operatin	g _	269324	Contact: Joe Hernandez								
Address: 2130 W. Bender Hobbs, NM 88240						Telephone No.: 575-738-1739							
Facility Name: Russell Turner Water Flood Skim Tank- Turner B.# 95						Facility Type: Injection Plant							
Surface Owner: Federal Mineral Owner:							Federal API No.: 3001				2		
				LOCA	TIC	N, OF REI	LEASE						
					h/South Line   Feet from the   E		East/West I West	st/West Line   County West   E		Eddy			
Latitude: 32.8199711236509 Longitude: -103.897239412252  NATURE OF RELEASE													
Type of Release: Produced Water / Oil							Rèlease: 586 / 6	66 Volume Recovered: 540 / 46					
Source of Release: Tank							lour of Occurrenc		Date and Hour of Discovery:				
							2	07/0	07/06/2012 6:30am				
Was Immediate Notice Given?   ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM							
By Whom? Joe Hernandez							Date and Hour 07/06/2012 9am						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*:  Describe Cause of Problem and Remedial Action Taken.*: Russell Turner Water flood plant pump went off and didn't call anyone on alarm, tanks filled up and skimmed over to skim tank and ran over tank. Haarmeyer electricians were called to fix problem, and found wires inside callout pannel box not properly connected. Connected/shorting out wires and alarms started working and calling out again.													
Describe Area Affected and Cleanup Action Taken.*: It ran approximately 1470 feet south west out of dike across road onto pasture. Pulled water/oil out of dike and tanks.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
							OIL CONSERVATION DIVISION						
Signature: Signature:						Signed By Mily Branches							
Printed Name	: Joe Herna	ndez			Approved by District Supervisor:								
Title: Production Foreman						Approval Date: Expiration Date:							
E-mail Addres						Conditions of			Attacl	ned [	]	_ ]	
Date: 07/09/2012 Phone: 575-942-9492 Attach Additional Sheets If Necessary						Remediation per OCD Rules &							

**Guidelines. SUBMIT REMEDIATION**