Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No 1004-0137
Expures October 31 2014

er an

SUNDRY	NOTICES AND REPORTS ON WELLS
	form for proposals to drill or to re-enter an
abandoned well.	Use Form 3160-3 (APD) for such proposals

Expires October 31, 2014
5. Lease Serial No. NM 06814
6. If Indian, Allottee or Tribe Name

abandoned well. (Jse Form 3160-3 (A	(PD) for such p	proposals	5.					
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well Oil Well Gas W		8. Well Name and No. Southern Union 2-Y							
2. Name of Operator TANDEM ENERGY CORPORATION	N				9. API Well No. 30-015-20248				
3a Address 2700 POST OAK BLVD, SUITE 1000 HOUSTON, TX 77056	3b. Phone No. (incl.)	(include area code) 10. Field and Pool or Exploratory Area							
4. Location of Well (Footage, Sec., T,R.,M., or Survey Description) 1980 FNL 667 FEL H-30-195-31E					11 County or Parish, State EDDY, NM				
12 CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICA	TE NATURE	OF NOTIC	E, REPORT OR OTH	ER DATA			
TYPE OF SUBMISSION	e. s		TYP	E OF ACTI	OF ACTION				
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture T	'reat	_	ection (Start/Resume)	=	er Shut-Off		
Subsequent Report	Casing Repair Change Plans	New Cons Plug and A	Abandon	=	nplete orarıly Abandon	Oth	er		
Final Abandonment Notice	Convert to Injection	Plug Back		Water	r Disposal				
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 1.) Circ hole with mud laden fluid. 2.) Spot cmt plug over perfs and base salt. 2.135 - 1817 3.) Tag plug @ 1817' 4.) Perf csg 50' below top salt (630') 5.) Squeeze perfs w/25 sx cmt. 6.) Tag plug @ 500 7.) Perf csg @ 60' 8.) Squeeze perfs w/cmt. Attempt to circ all csg to surface. 9.) Install dry hole marker and clean location. 10.) We will need a workover pit on this location. 4. If thereby certify that the foregoing is true and correct. Name (Printed/Typed)									
KERRICK P. Nolen	1 0 1	Tit	le Compl	BALCE	<u>-</u>				
Signature Date 9/25/11									
	THIS SPACE	FOR FEDERA	L OR ST	ATE OFF	ICE USE				
Conditions of approval, if any, are attached that the applicant holds legal or equitable the entire the applicant to conduct operations. Title 18 U.S. C. Section 1001 and Title 43	itle to those rights in the subje	ect lease which would	Office	SEI CFO			9-29-12		
fictitious or fraudulent statements or repre									

(Instructions on page 2)

Accepted for record NMOCD

· · · · · · · · · · · · · · · · · · ·		·	OPERATOR Tandem Energy WELL NAME Southern Union 2-Y API NO. 3001520248
HOLE SIZE CMT 150 SX CASING SIZE TO HOLE SIZE	1	Perfæ 60' Circi infont To sait, Perfæ 630, SOZ Cont to 50 Woc Tag	1980 (1) SEC38 TWN 195 RNG 31E T/SALT 553 B/SALT 1878
CMT ZOO SX,	To4 7		FORMATIONS: Yates 2052
	Toe ?	. 0 . 7	DVT
CASING SIZE TO 2286	155# 5/2" J-55 PBTD 2282		