`1Submit 3 Copies To Appropriate District	State of New Mex	rico	Form C-103
Office District I	Energy, Minerals and Natur	al Resources _	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	637	ĺ	WELL API NO.
District II	OIL CONSEDUATION	DIVISION	30-015-34062
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		· ·	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE STATE STATE	
District IV	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	·		
87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Carrington State
DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	ITON FOR PERMIT" (FORM C-101) FO	RSUCH	
1. Type of Well:			8. Well Number
Oil Well Gas Well 🖾 O	ither D	ECEIVED	#1
	, unca	ECCIVED	
2. Name of Operator	N	AY 2 4 2005	9. OGRID Number
Nadel and Gussman Permian, LLC	•	""	155615
3. Address of Operator		D-AHIEBIN	10. Pool name or Wildcat
601 N. Marienfeld Suite 508 Midland	l, Texas 79701		Empire South; Morrow
4. Well Location			
Unit Letter K · 1450)' feet from the South li	ne and 1 600'	feet from theWestline
Oint 150tto111,150			
Section 12 Town	ship 17-S Range 28-E	NMPM	County Eddy
SCCION 12 IOWI	11. Elevation (Show whether DR,		County Lady
	3,616' GL	KD, KI, OK, etc.	
Pit or Below-grade Tank Application (For pi		↑ 144 mmet he etteched	
Pit Location: UL_K_Sec_12_Twp_17-S_Rr	ng _28-E_ Pit type _Reserve _Depth to (Groundwater _150-200'	+_Distance from nearest fresh water well_ 1,000'+_
Distance from nearest surface water 1000'+_	Below-grade Tank Location UL	Sect Tw	p Rng ;
feet from the line and			
teet from the mile and	leet from themae		
12 Chark An	proprieta Poy to Indicata Na	eture of Notice I	Panort or Other Data
	propriate Box to Indicate Na		
NOTICE OF INT	ENTION TO:	SUBS	SEQUENT REPORT OF:
	ENTION TO:		SEQUENT REPORT OF:
NOTICE OF INTI	ENTION TO: PLUG AND ABANDON	SUBS REMEDIAL WORK	SEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTI	ENTION TO:	SUBS	SEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND
NOTICE OF INTI	ENTION TO: PLUG AND ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRIL	SEQUENT REPORT OF: ALTERING CASING DELING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTIPERFORM REMEDIAL WORK I	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	SUBS REMEDIAL WORK COMMENCE DRILL CASING TEST AN	SEQUENT REPORT OF: ALTERING CASING DELING OPNS. PLUG AND DELING ABANDONMENT
NOTICE OF INTIPERFORM REMEDIAL WORK I	ENTION TO: PLUG AND ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRIL	SEQUENT REPORT OF: ALTERING CASING DELING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTIPERFORM REMEDIAL WORK I	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRILL CASING TEST AN CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D
NOTICE OF INTIPERFORM REMEDIAL WORK I	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	SUBS REMEDIAL WORK COMMENCE DRILL CASING TEST AN	SEQUENT REPORT OF: ALTERING CASING DELING OPNS. PLUG AND ABANDONMENT D
NOTICE OF INTIPERFORM REMEDIAL WORK I TEMPORARILY ABANDON OPERATION OTHER:	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRILL CASING TEST AN CEMENT JOB OTHER: Amended	SEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D
NOTICE OF INTIPERFORM REMEDIAL WORK ITEMPORARILY ABANDON OF ITEMPO	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cd operations. (Clearly state all p	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and	BEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D Report give pertinent dates, including estimated date
NOTICE OF INTIPERFORM REMEDIAL WORK I TEMPORARILY ABANDON OF TEMPOR	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cd operations. (Clearly state all p	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and	BEQUENT REPORT OF: ALTERING CASING LING OPNS. PLUG AND ABANDONMENT D Report
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and run 6 joints 13 3/8	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta	ALTERING CASING ALTERING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and run 6 joints 13 3/8 1/4/KKD29 + 2%D46 lead. Cement w/ 47bbls C	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta	ALTERING CASING ALTERING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and run 6 joints 13 3/8	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta	ALTERING CASING ALTERING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and rum 6 joints 13 3/8 3/#KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP a	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to	ALTERING CASING ALTERI
NOTICE OF INTERPORT OF INTERPOR	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to	ALTERING CASING ALTERING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and rum 6 joints 13 3/8 3/#KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP a	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to	ALTERING CASING ALTERI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and rum 6 joints 13 3/8 V#KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP a 05/19/05 P/U and R/U BHA and TIH tagged cem 30min.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOo ment @ 183' circ. and WOC. Drill cement	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to c for 18 hrs. and plug to 230' and tes	ALTERING CASING ABANDONMENT ABANDONM
NOTICE OF INTIPERSON NOTICE OF INTIPERSON REMEDIAL WORK ITEMPORARILY ABANDON ITEMPORARI	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOo ment @ 183' circ. and WOC. Drill cement ove is true and complete to the be-	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to c for 18 hrs. and plug to 230' and tes st of my knowledge	ALTERING CASING ABANDONMENT ABANDONMENT BY ABANDO
NOTICE OF INTIPERSON NOTICE OF INTIPERSON REMEDIAL WORK ITEMPORARILY ABANDON ITEMPORARI	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOo ment @ 183' circ. and WOC. Drill cement ove is true and complete to the be-	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to c for 18 hrs. and plug to 230' and tes st of my knowledge	ALTERING CASING ABANDONMENT ABANDONM
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and rum 6 joints 13 3/8 13/4/KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP a 05/19/05 P/U and R/U BHA and TIH tagged cem 30min. I hereby certify that the information aborrade tank has been/will be constructed or clo	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOo ment @ 183' circ. and WOC. Drill cement ove is true and complete to the be- used according to NMOCD guidelines Seed according to NMOCD guidelines	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit o	ALTERING CASING ABANDONMENT ABANDONMENT BY ABAN
NOTICE OF INTIPERSON NOTICE OF INTIPERSON REMEDIAL WORK ITEMPORARILY ABANDON ITEMPORARI	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all p.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOo ment @ 183' circ. and WOC. Drill cement ove is true and complete to the be- used according to NMOCD guidelines Seed according to NMOCD guidelines	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit o	ALTERING CASING ABANDONMENT ABANDONMENT BY ABANDO
NOTICE OF INTERPORT OF INTERPOR	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all pt.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO ment @ 183' circ. and WOC. Drill cement ove is true and complete to the bessed according to NMOCD guidelines TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit C Staff Engineer	ALTERING CASING ALTERI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and rum 6 joints 13 3/8 13/4/KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP a 05/19/05 P/U and R/U BHA and TIH tagged cem 30min. I hereby certify that the information aborrade tank has been/will be constructed or clo	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all pt.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO ment @ 183' circ. and WOC. Drill cement ove is true and complete to the bessed according to NMOCD guidelines TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit C Staff Engineer	ALTERING CASING ABANDONMENT ABANDONMENT BY ABAN
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and run 6 joints 13 3/8 1/4/KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP at 05/19/05 P/U and R/U BHA and TIH tagged cem 30min. I hereby certify that the information ab grade tank has been/will be constructed or closs SIGNATURE Type or print name Josh Fernau	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all pt.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO ment @ 183' circ. and WOC. Drill cement ove is true and complete to the bessed according to NMOCD guidelines TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit C Staff Engineer	ALTERING CASING ABANDONMENT ABANDONMENT BY ABAN
NOTICE OF INTIPERSON NOTICE OF INTIPERSON REMEDIAL WORK ITEMPORARILY ABANDON ITEMPORARI	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Completions. (Clearly state all percent). SEE RULE 1103. For Multiple and choke manifold (2000 psi OK. WOO ment (2018) and choke manifold (2000 psi OK. WOO ment (2018) are and complete to the best of according to NMOCD guidelines. E-mail address: jo	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit C Staff Engineer	ALTERING CASING ALTERI
NOTICE OF INTI PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/18/05 R/U casing crew and rum 6 joints 13 3/8 //#KKD29 + 2%D46 lead. Cement w/ 47bbls C well head test to 500 psi ok. N/U and test BOP a 05/19/05 P/U and R/U BHA and TIH tagged cem 30min. I hereby certify that the information abgrade tank has been/will be constructed or clo SIGNATURE	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all pt.). SEE RULE 1103. For Multiple 8" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO ment @ 183' circ. and WOC. Drill cement ove is true and complete to the beseed according to NMOCD guidelines TITLE E-mail address: jo	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit C Staff Engineer	ALTERING CASING ABANDONMENT ABANDONMENT BY ABAN
NOTICE OF INTIPERSON NOTICE OF INTIPERSON REMEDIAL WORK ITEMPORARILY ABANDON ITEMPORARI	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ded operations. (Clearly state all pt.). SEE RULE 1103. For Multiple B" H-40 48# casing 250' set @ 230'. R/U + 2%S-1 + ½#KKD29 tail. Plug down @ and choke manifold @ 1000 psi OK. WOO ment @ 183' circ. and WOC. Drill cement ove is true and complete to the bessed according to NMOCD guidelines TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Amended ertinent details, and e Completions: Atta Schlumberger and circ h 6:00 pm circ. 10 bbls to C for 18 hrs. and plug to 230' and tes st of my knowledge l, a general permit C Staff Engineer	ALTERING CASING ABANDONMENT ABANDONMENT BY ABAN