	State of r	New Me	xico		Form C-103
Office District I	Energy, Minerals a	and Natur	ral Resources		March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	~. .			WELL API NO.	
District II				30-015-34062	
1301 W. Grand Ave., Artesia, NM 88210	1501 W. Glada Ave., Alaska, two 60210			5. Indicate Type	of Lease
District III	1000 Bio Desper Dd. Artes NW 97410			STATE	
District IV Santa Fe, NM 87505			⁷ 505	6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM					
87505					
· · · · · · · · · · · · · · · · ·	ES AND REPORTS ON				r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL, OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Carrington State	
PROPOSALS.)					
1. Type of Well:				8. Well Number	
Oil Well Gas Well 🖾 Other				#1	
	, (1144)	REC	EIVED	o ocento vi	
2. Name of Operator				9. OGRID Numl	per
Nadel and Gussman Permian, LLC		MAY.	2 7 2005	155615	
3. Address of Operator				10. Pool name or Wildcat	
601 N. Marienfeld Suite 508 Midland	, Texas 79701	ومروبيون=	JULICOM	Empire South; M	orrow
4. Well Location					
Unit LetterK:1,450	'feet from theS	outhl	ine and1,600'	feet from the _	Westline
Section 12 Town	ship 17-S Range		NMPM		Eddy
	11. Elevation (Show who	ether DR,	RKB, RT, GR, etc.)		
		·	·		
Pit or Below-grade Tank Application (For pit		res, a form	C-144 must be attached	D	
Pit Location: UL_K_Sec_12_Twp_17-S_Rn	s 28.E Pit tyne Reserve	Denth to	Croundwater 150-200	'+ Distance from near	rest fresh water well 1.000'+
1					ŀ
Distance from nearest surface water 1000'+_	Below-grade Tank Loc	ation UL_	SectT	vp	;
feet from theline and	feet from the	_line			
12 Check An	propriate Roy to Inc	dicate N	ature of Notice	Report or Other	· Data
NOTICE OF INTE	PLUG AND ABANDON CHANGE PLANS		SUBS REMEDIAL WORK COMMENCE DRI	SEQUENT RE	
NOTICE OF INTERPRETATION OF TEMPORARILY ABANDON OF TEMPORARILY ABAND	ENTION TO: PLUG AND ABANDON	_ 	SUBSTREMEDIAL WORK COMMENCE DRICCEST AND CEMENT JOB	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF INTERPRETATION OF TEMPORARILY ABANDON OF THE PULL OR ALTER CASING OR ALTER CASING OF THE PULL OR ALTER CASING OF THE PULL OR ALTER C	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE		SUBSTREMEDIAL WORK COMMENCE DRICE CASING TEST AN	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF INTERPRETATION OF TEMPORARILY ABANDON OF TEMPORARILY ABAND	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION		SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: Amende	SEQUENT RE LLING OPNS. ID Report	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF INTERPRETATION OF TEMPORARILY ABANDON OF TEMPORARILY ABAND	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. Fo	State all por Multipl	SUBS REMEDIAL WORK COMMENCE DRING CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and the Completions: Att	SEQUENT RE LLING OPNS. ID d Report give pertinent dat ach wellbore diagram	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date ram of proposed completion
NOTICE OF INTERPRETATION OF TEMPORARILY ABANDON OF TEMPORARILY ABAND	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. Fo un pipe. R/U lay down machin	State all por Multiple	SUBS REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and the Completions: Att	SEQUENT RE LLING OPNS. ID d Report d give pertinent dat ach wellbore diagrameting and R/U casing	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40#
NOTICE OF INTERMEDIAL WORK PERFORM REMEDIAL REM	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For pipe. R/U lay down maching in hole. Test line and pump 2: ng. N/U B-section, BOP, test	state all pror Multipl	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 5 poz and 47 bbls class	SEQUENT RE LLING OPNS. ID d Report give pertinent dat ach wellbore diagrach wellbore diagracheting and R/U casing C+ adds w/ 180bbls di	PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON O PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test as for 30 min OK.	state all por Multiple and laid a 27 bbls 35/6 choke and F	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class BOP tested well. Strap B	SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D
NOTICE OF INTERPRETATION NOTICE OF INTERPRETATION OF INTERPRETATIO	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ang. N/U B-section, BOP, test as for 30 min OK.	state all por Multiple ine and laid a 27 bbls 35/6 choke and E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class 30P tested well. Strap B	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON O PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ang. N/U B-section, BOP, test as for 30 min OK.	state all por Multiple ine and laid a 27 bbls 35/6 choke and E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class 30P tested well. Strap B	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON G PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work, or recompletion. 05/22/05 Circ. and condition hole TOOH to re N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close approved plan	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test sist for 30 min OK. is true and complete to the ed according to NMOCD	state all por Multiple and laid of 27 bbls 35/6 choke and E best of my	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and the Completions: Att down DC's held safety in the Completions of poz and 47 bbis class BOP tested well. Strap Boy knowledge and belies The Knowledge and belies The Completion of the Comp	SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON O PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work, or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test sist for 30 min OK. is true and complete to the ed according to NMOCD	state all por Multiple and laid of 27 bbls 35/6 choke and E best of my	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class 30P tested well. Strap B	SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON O PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close approved plan SIGNATURE Furnamental Constructed Furnamental Const	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test sai for 30 min OK. is true and complete to the ed according to NMOCD TITLE	state all por Multiple ine and laid of 27 bbls 35/6 choke and E best of my guidelineStaff E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class BOP tested well. Strap B y knowledge and belie s 🖾, a general perm ngineerDA	SEQUENT RE LLING OPNS. ID d Report I give pertinent date arch wellbore diagonate meeting and R/U casing C + adds w/ 180bbls diagonate with the control of the control o	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON G PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work, or recompletion. 05/22/05 Circ. and condition hole TOOH to re N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close approved plan	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test sist for 30 min OK. is true and complete to the ed according to NMOCD	state all por Multiple ine and laid of 27 bbls 35/6 choke and E best of my guidelineStaff E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and the Completions: Att down DC's held safety in the Completions of poz and 47 bbis class BOP tested well. Strap Boy knowledge and belies The Knowledge and belies The Completion of the Comp	SEQUENT RE LLING OPNS. ID d Report I give pertinent date arch wellbore diagonate meeting and R/U casing C + adds w/ 180bbls diagonate with the control of the control o	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON O PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487' circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close approved plan SIGNATURE Furnamental Constructed Furnamental Const	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test sai for 30 min OK. is true and complete to the ed according to NMOCD TITLE	state all por Multiple ine and laid of 27 bbls 35/6 choke and E best of my guidelineStaff E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class BOP tested well. Strap B y knowledge and belie s 🖾, a general perm ngineerDA	SEQUENT RE LLING OPNS. ID d Report I give pertinent date arch wellbore diagonate meeting and R/U casing C + adds w/ 180bbls diagonate with the control of the control o	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON C PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487" circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close approved plan C SIGNATURE F Type or print name Josh Fernau Type or print name Josh Fernau Type or State use)	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For the pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test is for 30 min OK. is true and complete to the ed according to NMOCD TITLE E-mail address:	state all por Multiple ine and laid of 27 bbls 35/6 choke and E best of my guidelineStaff E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class BOP tested well. Strap B y knowledge and belie s 🖾, a general perm ngineerDA	SEQUENT RE LLING OPNS. ID A Report I give pertinent date arch wellbore diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering and R/U casing C + adds w/ 180bbls diagonering	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out
NOTICE OF INTER PERFORM REMEDIAL WORK F TEMPORARILY ABANDON C PULL OR ALTER CASING F OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 05/22/05 Circ. and condition hole TOOH to ru N-80 LTC casing set @ 2,487" circ. and condition Schlumberger and WOC. 05/23/05 N/D, set slips and cut off 9 5/8" casin cement and float collar. Tested casing to 1,000 p I hereby certify that the information above it tank has been/will be constructed or close approved plan C SIGNATURE F Type or print name Josh Fernau Type or print name Josh Fernau Type or State use)	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION ed operations. (Clearly). SEE RULE 1103. For an pipe. R/U lay down maching in hole. Test line and pump 2: ag. N/U B-section, BOP, test sai for 30 min OK. is true and complete to the ed according to NMOCD TITLE	state all por Multiple ine and laid of 27 bbls 35/6 choke and February guidelineStaff E	SUBS REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: Amende Dertinent details, and le Completions: Att down DC's held safety m 55 poz and 47 bbls class BOP tested well. Strap B y knowledge and belie s 🖾, a general perm ngineerDA	SEQUENT RE LLING OPNS. ID A Report I give pertinent date arch wellbore diagrameting and R/U casing C + adds w/ 180bbls dia	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date ram of proposed completion crew. Run 58 joints of 9 5/8" 40# splacement circ. to surface. R/D TIH to bottom WOC. Drill out