Form 3160-3 1 (August 1999)

N.M. Oil Cons. DIV-Dist. 2

DEPARTMENT OF THE INTER 1301 W. Grand Avenue BUREAU OF LAND MANAGEMENT THE SIA, NIVI 88210

FORM APPROVED OMB NO. 1004-0136 Expires: November 30, 2000

APPLICATION FOR PERMIT TO DRI	LL OR REENTER		NM-0354232		
la. Type of Work 🔲 DRILL REE	NTER	6.	If Indian, Allotee o	r Tribe Name	
1b. Type of Well Oil Well Gas Well Other	Single Zone Multiple Zon	ne 7.	Unit or CA Agreen	nent Name and No.	
2. Name of Operator		8.	Lease Name and W	'ell No.	
OXY USA WTP Limited Partnership	192463		Elizando A F		
3a. Address	3b. Phone No. (include area co	de) 9.	API Well No.		
P.O. Box 50250 Midland, TX 79710-0250	432-685-5717		30-015 3	4149	
4. Location of Well (Report location clearly and in accordance with any At surface 1650 FSL 660 FEL NESE(I)		10.	Field and Pool, or I Burton Flat		
At proposed prod. zone	RECEIVI	ו עב	Sec., T., R., M., or Sec 21 T21S	Blk. and Survey or Are R27F	
14. Distance in miles and direction from nearest town or post office*	JUN 0 3 7	JU5 12.	County or Parish	13. State	
	Carlsbad. NM ODD:AGT		ldv	NM	
15. Distance from proposed*	16. No. of Acres in lease		ng Unit dedicated to		
location to nearest property or lease line, ft. (Also to nearest drg. unit line, if any)	320		320		
					
18. Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft.	19. Proposed Depth	20.BLM/	BIA Bond No. on		
2849'	11800'		93127	74	
21. Elevations (Show whether DF, KDB, RT, GL, etc.	22. Approximate date work will sta	rt*	23. Estimated duration		
3225'	9/1/05	İ	30) days	
	24. Attachments CARLS	BAD CO	NTROLLED W		
The following, completed in accordance with the requirements of Onshore	e Oil and Gas Order No. 1, shall be attached	d to this fo	orm:		
 Well plat certified by a registered surveyor. A Drilling Plan A Surface Use Plan (if the location is on National Forest System Land SUPO shall be filed with the appropriate Forest Service Office). 	4. Bond to cover the operati Item 20 above). 5. Operator certification. 6. Such other site specific in authorized officer.				
25. Signuature	Name (Printed/Typed)		Date		
Va Stat	David Stewart		_	3/1/05	
Title					
Sr. Regulatory Analyst					
Approved by (Signautre) /s/ Joe G. Lara	Name (Printed/Typed) /S/ Jo	oe G. I	ara	JUN - 1 2005	
Title ACTING FIELD MANAGER	Office CARLSBAD	FIELL	OFFICE	JON 1 2000	
Application approval does not warrant or certify that the applicant holds	legal or equitable title to those rights in	the subject	lease which would	entitle the applicant to	
conduct operations thereon. Conditions of approval, if any, are attached.	APPROVA				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it United States any false, fictitious or fraudulent statements or representation		willfully to	make to any depa	rtment or agency of the	

*(Instructions on Reverse)

APPROVAL SUBJECT TO GENERAL REQUIREMENTS
AND SPECIAL STIPULATIONS **ATTACHED**

Attachment C-101 Elizando A Federal #7 1650 FSL 660 FEL NESE(I) SEC 21 T21S R27E Eddy County, NM Federal Lease No. NM-0354232

PROPOSED TD:

11800' TVD

BOP PROGRAM:

0-600'

None

600-2700'

13-3/8" 3M annular preventer, to be used as

divertor only.

2700-11800'

11" 5M blind pipe rams with 5M annular

preventer and rotating head below 8500'.

CASING:

Surface:

13-3/8" OD 48# H40 ST&C new casing set at 600'

17-1/2" hole

Intermediate:

9-5/8" OD 36# K55 ST&C new casing from 0-2700'

12-1/4" hole

Production:

5-1/2" OD 17# N80-HP110 LT&C new casing from 0-11800'

8-3/4" hole 8400'-N80 3400'-HP110

CEMENT:

Surface - Circulate cement with 360sx HES light premium plus w/ 2% $CaCl_2 + .25\#/sx$ Flocele followed by 250sx PP w/ 2% $CaCl_2 + .25\#/sx$ Flocele.

Intermediate - Circulate cement with 595sx Interfill C w/ .25#/sx Flocele followed by 200sx PP w/ 2% CaCl₂.

Production - Cement with 350sx Interfill H w/ .1% HR-7 followed by 400sx Super H w/ .5% HR-344 + .4% CFR-3 + 5#/sx Gilsonite + 1#/sx salt + .2% HR-7. Estimated top of cement is 8000'.

Note: Cement volumes may need to be adjusted to hole caliper.

MUD:

0-600'

Fresh water/native mud. Lime for pH control

(9-10). Paper for seepage. Wt 8.7-9.2 ppg, Vis 32-34 sec

600-27001

Fresh/*Brine water. Lime for pH control (10.0-

10.5). Paper for seepage.

Wt 8.3-9.0/10.0-10.1ppg, Vis 28-29 sec

*Fresh water will be used unless chlorides in

the mud system increases to 20000PPM.

2700-80001

Fresh water. Lime for pH control (9-9.5). Paper

for seepage.

Wt 8.3-8.5 ppg, Vis 28-29 sec

8000-10000'

Cut brine. Lime for pH control (10-10.5).

Wt 9.6-10.0 ppg, Vis 28-29sec

10000-11800

Mud up with an Duo Vis/Flo Trol mud system.

Wt 9.6-10.0ppg, Vis 32-36sec, WL<10cc

HECENED 52

025 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Form C-144

March 12, 2004

Pit or Below-Grade Tank Registration or Closure
Is pit or below-grade tank covered by a "general plan"? Yes No

	r below-grade tank \(\infty\) Closure of a pit or below-g			
Operator: _Occidental U.S.A. W.T.P. Limited PartnershipTelepho Address: P.O. Box 50250, Midland, TX 79710		R_27 E		
Pit Type: Drilling ☑ Production ☐ Disposal ☐ Workover ☐ Emergency ☐ Lined ☑ Unlined ☐ Liner type: Synthetic ☑ Thickness12_mil Clay ☐ Volume 11,000_bbl	Below-grade tank Volume:bbi Type of fluid: Construction material: Double-walled, with leak detection? Yes			
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) 10 (0 points)		
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points) 0		
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points) 0		
	Ranking Score (Total Points)	Total 10		
If this is a pit closure: (1) attach a diagram of the facility showing the pit's onsite offsite If offsite, name of facility date. (4) Groundwater encountered: No Yes If yes, show depth belo diagram of sample locations and excavations. I hereby certify that the information above is true and complete to the best of been/will be constructed or closed according to NMOCD guidelines , a Date: 1/19/05		ction taken including remediation start date and end uple results. (5) Attach soil sample results and a nee above-described pit or below-grade tank has		
Printed Name/Title Don Thompson/HES Spec. Signat Your certification and NMOCD approval of this application/closure does not otherwise endanger public health or the environment. Nor does it relieve the regulations.	relieve the operator of liability should the contents	of the pit or tank contaminate ground water or ny other federal, state, or local laws and/or		
Approval: Date: Print MARATE/Title 0 2005 July Dap P	Signature			

Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS

<u>NM2927</u>1 Nm 0354232

Do not use this	form for proposals to drill or to re-enter an
	Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

abandoned well. Use For	m 3160-3 (APD) for	r such proposals.		, -	
SUBMIT IN TRIPLICATE -	Other instructions	s on reverse side		7. If Unit or (CA/Agreement, Name and/or No
Type of Well Oil Well	8. Well Name Elizando A	e and No. A Federal #7			
OXY USA WTP Limited Partnership		192	2463	9. API Well I	No.
3a. Address		3b. Phone No. (include ar	rea code)	30-015-	
P.O. Box 50250, Midland, TX 79710- 4. Location of Well (Footage, Sec., T., R., M., or Survey in 1980 FSL 660 FEL NESE(I) Sec 21 T	Description)	432-685-5717		10. Field and Burton Fla	Pool, or Exploratory Area at Morrow
1960 F3E 000 FEE NESE(1) Sec 21 F	213 R27L			11. County o	r Parish, State
				Eddy	NM
12. CHECK APPROPRIATE	BOX(ES) TO INI	DICATE NATURE OF	NOTICE, REPO	ORT, OR OT	HER DATA
TYPE OF SUBMISSION		TYI	PE OF ACTION		
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off
_	Alter Casing	Fracture Treat	Reclamation	n	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	•	X Other Move
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporaril	y Abandon	Surface Location
	Convert to Injecti	on Plug Back	Water Disp	osal	
Per BLM Request the surface locat Exhibit's B.	tion was moved.	Please see attach	ed for an am	ended C-10	2 plat and
New Location: 1980 FSL 660 FEL N	NESE(I) Sec 21	T21S R27E			
01d Location: 1650 FSL 660 FEL M	NESE(I) Sec 21	T21S R27E			
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart 		Title Sr Re	egulatory Ana	alvet	
David Scewart			3 (05	iiyst	
TUI	S SPACE FOR FEI	DERAL OR STATE OF			
Approved by	O OFACE FOR FEI			ח	Pate UN - 1 2005
/S/ JOE (1. Lara Conditions of approval, if any, are attached. Approval	of this notice does not t	Wallall Of Office	MANAGI		
certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations t	thereon.	CA	ARLSBAD	FIELD (OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

State of New Mexico

DISTRICT I

Knersy, Minerals and Natural Resources Department

DISTRICT II 1301 W. GRAND AVENUE, ARTESIA, NM 88210

OIL CONSERVATION DIVISION 1220 SOUTH ST. FRANCIS DR. Santa Fe, New Mexico 87505

Form C-102 Revised JUNE 10, 2003 Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

DISTRICT III

DISTRICT IV

1000 Rio Brazos Rd., Aztec, NM 87410

WELL LOCATION AND ACREAGE DEDICATION PLAT

SAMENDED REPORT

API Number	Pool Code	Pool Nam	e		
30-015-	73 280	73280 But an Flat			
Property Code	Propert	Weil Number			
	CONTELLIZA	CANDO A Federal	7		
OGRID No.	-	r Name	Elevation		
192463	OXY U.S.A.	W.T.P., LP	3226'		


Surface Location


UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	Rast/West line	County
1	21	21-S	27-E		1980	SOUTH	660	EAST	EDDY

Bottom Hole Location If Different From Surface

UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	Bast/West line	County
Dedicated Acre	s Joint o	r Infill Co	nsolidation (Code Or	ler No.				<u> </u>
320	Y								

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION






PROVIDING SURVEYING SERVICES
SINCE 1948

JOHN WEST SURVEYING COMPANY
412 N. DAL PASO
HOBBS, N.M. 88240
(506) 389-3117

OXY ELIZANDO A #7 WELL
LOCATED 1980 FEET FROM THE SOUTH LINE
AND 660 FEET FROM THE EAST LINE OF SECTION 21,
TOWNSHIP 21 SOUTH, RANGE 27 EAST, N.M.P.M.,
EDDY COUNTY, NEW MEXICO.

Survey Date: 3,	/22/05	٥	Sheet	1	of	1	Sheets
W.O. Number: 05.	Dr E	By: J.R.		R	ev 1:	N/A	
Date: 3/29/05	Disk: CD#	4 5	0511	049.	3	Scal	e:1"=100'

VICINITY MAP




SCALE: 1" = 2 MILES

SEC. <u>21</u> T	WP. <u>21-S</u> RGE, <u>27-E</u>
SURVEY	N.M.P.M.
COUNTY	EDDY
DESCRIPTION	1980' FSL & 660' FEL
ELEVATION	3226'
OPERATOR	OXY U.S.A. W.T.P., LP
LEASE	OXY FUZANDO A



PROVIDING SURVEYING SERVICES SINCE 1946 JOHN WEST SURVEYING COMPANY 412 N. DAL PASO HOBBS, N.M. 88240 (805) 383-3117


LOCATION VERIFICATION MAP



SCALE: 1" = 2000'

CONTOUR INTERVAL: CARLSBAD EAST, N.M. – 10'


SEC. 21 TWP. 21-S RGE. 27-E
SURVEYN.M.P.M.
COUNTYEDDY
DESCRIPTION 1980' FSL & 660' FEL
ELEVATION 3226'
OPERATOR OXY U.S.A. W.T.P., LP
LEASEOXY ELIZANDO A
U.S.G.S. TOPOGRAPHIC MAP CARLSBAD EAST, N.M.






ANNULAR PREVENTOR

TO BE USED AS DIVERTOR ONLY





11" 5000# ram type preventers with one set blind rams and one set pipe rams and a 5000# annular type preventer. A choke manifold and 120 gallon accumulator with floor and remote operating stations and auxiliary power system.

Choke Manifold

Multi-Point Surface Use and Operations Plan Elizando A Federal #7 Page 4

- H. The well site, if a producer, will be maintained and kept clean of all trash and litter which detracts from the surrounding environment. Equipment will be maintained in accordance with good operating practice.
- I. After the wellsite is cleaned and pits and sumps backfilled, any obstruction to the natural drainage will be corrected by ditching or terracing. All disturbed areas, including any access road no longer needed, will be ripped. Those areas will be reseeded with grass if, in the opinion of the land owner, it is required.

13. Operator's Representatives and Certification

The field representative responsible for assuring compliance with the approved surface use and operations plan are as follows:

John Erickson Production Coordinator P.O. Box 69 Hobbs, New Mexico 88240 Office Phone: 505-393-2174 Cellular: 505-390-6426

Calvin C. (Dusty) Weaver Operation Specialist P.O. Box 2000 Levelland, TX 79336 Office Phone: 806-229-9467 Cellular: 806-893-3067 Joe Fleming Drilling Coordinator P.O. Box 50250 Midland, TX 79710-0250 Office Phone: 915-685-5858

Terry Asel Operation Specialist 1017 W. Stanolind Rd. Hobbs, NM 88240 Office Phone: 505-397-8217 Cellular: 505-631-0393

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drill site and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and, that the work associated with the operations proposed herein will be performed by OXY USA WTP Limited Partnership and its contractors and sub-contractors in conformity with this plan and the terms and conditions under which it/is approved.

3/8/2005

DATE


Scott Gengler

Engineering Advisor

432-685-5825

South Permian Asset Team

OXY USA WTP Limited Partnership



OXY USA WTP Limited Partnership PO Box 50250 Midland, TX 79710

Hydrogen Sulfide (H2S) Contingency Plan

For

Elizando "A" No. 7 1650 ft. FSL, 660 ft. FEL Sec 21, T21S, R27E Eddy County, NM

And

McVay Drilling Co., Rig No. 8

TABLE OF CONTENTS

<u>ITEM</u>	<u>PAGE</u>
PREFACE	3
LOCATION MAP	4
RIG SKETCH	. 5
EMERGENCY RESPONSE ACTIVATION AND GENERAL RESPONSIBILITIES	6
SPECIFIC EMERGENCY GUIDANCE - H2S Release - Well Control	. 8
PUBLIC RELATIONS	. 13
PHONE CONTACTS - OP DOWNHOLE SERVICES GROUP	. 14
EMERGENCY PERSONELL NOTIFICATION NUMBERS	. 13
PHONE CONTACTS - OP PRODUCTION AND PLANT PERSONNEL	. 15
PHONE CONTACTS – OP HES PERSONNEL	. 16

PREFACE

An effective and viable Contingency Plan is intended to provide prior planning and guidance in responding to emergency incidents. The primary considerations in its development are protection of personnel, the public, company and public property, and the environment.

Although the plan addresses varied emergency situations which may occur, it recognizes that flexibility and the use of the organization's knowledge and experience is critical to safe resolution of emergency incidents. Response actions outlined in the plan provide a framework, which may be placed into operation without confusion. These actions should promote quick and decisive actions during the critical initial period and immediately following an emergency. As the response progresses, additional guidelines and procedures may need to be implemented as the situation dictates. In addition, all emergency incidents must be properly reported per the Oxy Incident Reporting and Notification Policy, state and federal requirements, etc.

This Contingency Plan is intended for use on Oxy Downhole Services Group projects and the operations within their area of responsibility, such as drilling, critical well work, etc.

Elizando A No. 7


LAT. - 32°27'45.47"

LONG. - 104°12'16.67"W


Y = 532049.0 N

X = 544835.7 E





From the intersection of US Hwy. 62-180 and the Carlsbad Relief Route go north-northwest approx. 1 mile and turn left onto a 20' wide caliche road. Go west approx. 0.66 of a mile and turn right at road intersection. Go north 0.6 then turn east and proceed for 0.5 miles



EMERGENCY RESPONSE ACTIVATION AND GENERAL RESPONSIBILITIES

Activation of the Emergency Action Plan

- A. In the event of any emergency situation, all personnel on location should first ensure that the following items are initiated. After that, they should refer to the appropriate Specific Emergency Guidance sections on pages ten (10) through twelve (12) in this document for further responsibilities:
 - 1. Notify the senior ranking contract representative on site.

2. Notify Oxy representative in charge.

- 3. Notify civil authorities if the Oxy Representative can not be contacted and the situation dictates.
- 4. Perform rescue and first aid as required (without jeopardizing additional personnel).

General Responsibilities

Oxy Permian Personnel:

- A. Operations Specialist: The Oxy Drilling/Critical Well Servicing Operations Specialist or contract personnel serving in that capacity will serve as Operations Chief Officer for all emergency incidents. The Operations Chief Officer is responsible for:
 - 1. Notification to the Downhole Services Team Leader of the incident occurrence.
 - 2. Notification to the local RMT/PMT leader of the incident occurrence, and the need for the designated local RMT/PMT Incident Commander to act in that capacity for the response effort.
 - 3. Sole control of all tactical activities directed toward reducing the immediate hazard, establishing situational control and restoring the operations to a non-emergency state.
- B. Local RMT/PMT Designated Incident Commander: The Oxy local RMT/PMT Designated Incident Commander will serve as the overall Incident Commander for the drilling or critical well servicing emergency incident. The Incident Commander is responsible for:
 - 1. Coordinating with the Downhole Services Team Leader for notification to the Oxy Crisis Management team of the incident occurrence.
 - 2. Establishing and managing the overall incident command structure and response from inception through restoration of normal activities in the area.
- C. Downhole Services HES Tech: The Downhole Services HES Tech (or his designate) is responsible for reporting to the incident as soon as reasonably possible, to provide support to the response effort as required by the Operations Chief Officer or the Incident Commander.

Contract Drilling Personnel will immediately report to their assigned stations and perform their duties as outlined in the appropriate Specific Emergency Guidance sections on pages ten (10) through twelve (12) in this document.

Other Contractor Personnel will report to the safe briefing area to assist Oxy personnel and civil authorities as requested when it is safe to do so and if they have been adequately trained in their assigned duties.

Civil Authorities (Law Enforcement, Fire, and EMS) will be responsible for:

- 1. Establishing membership in the Unified Incident Command.
- 2. As directed by the Incident Commander and the Unified Command, control site access, re-route traffic, and provide escort services for response personnel.
- 3. Perform all fire control activities in coordination with the Unified Command.
- 4. Initiate public evacuation plans as instructed by the Incident Commander.
- 5. Perform rescue or recovery activities with coordination from the Unified Command.
- 6. Provide medical assistance as dictated by the situation at hand.

H2S RELEASE

The following procedures and responsibilities will be implemented on activation of the H2S siren and lights.

All Personnel:

1. On alarm, don escape unit (if available) and report to upwind briefing area.

Rig Manager/Tool Pusher:

- 1. Check that all personnel are accounted for and their condition.
- 2. Administer or arrange for first aid treatment, and /or call EMTs as needed.
- 3. Identify two people best suited to secure well and perform rescue, and instruct them to don SCBA.
- 4. Notify Contractor management and Oxy Representative.
- 5. Remain at the briefing area, assess and monitor personnel and overall situation for hazards or conditions that might warrant a change in the action plan.

Two People Responsible For Shut-in and Rescue:

- 1. Don SCBA and acquire tools to secure well and perform rescue, i.e., wrenches, retrieval ropes, etc.
- 2. Utilize the buddy system to secure well and perform rescue(s).
- 3. Return to the briefing area and stand by for further instructions.

All Other Personnel:

1. Isolate the area and prevent entry by other persons into the 100 ppm ROE. Additionally the first responder(s) must evacuate any public places encompassed by the 100 ppm ROE. First responder(s) must take care not to injure themselves during this operation. Company and/or local officials must be contacted to aid in this operation. Evacuation of the public should be beyond the 100 ppm ROE.

Oxy Representative:

- 1. Remain at the briefing area, assess and monitor personnel and overall situation for hazards or conditions that might warrant a change in the action plan.
- 2. Notify Operation Specialists or Team Leader and RMT Leader or Local Incident Commander, and Police, Fire Department, or other local emergency services as required.

Training

All responders must have training in the detection of H2Sm measures for protection against the gas, equipment used for protection and emergency response. Weekly drills by all crews will be conducted and recorded in the IADC daily log. Additionally, responders must be equipped with H2S monitors at all times

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO2). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally the NM State Police shall be the Incident Command of any major release.

Characteristics of H2S and SO2

Common Name	Chemical Fromula	Specific Gravity	Threshold Limit	Hazardous Limit	Lethal Concentration
Hydrogen Sulfide	H ₂ S	1.189 Air = 1	10 ppm	100 ppm	600 ppm
Sulfur Dioxide	SO ₂	2.21 Air = 1	2 ppm	N/A	1000 ppm

Contacting Authorities

Oxy Permian personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such type and volume of release, wind direction, location of release, etc. Be prepared with all information available. The following call list of essential and potential responders has been prepared for use during a release. This response plan must be in coordination with the State of New Mexico's 'Hazardous Materials Emergency Response Plan' (HMER).

WELL CONTROL

The following procedures will be implemented when a loss of primary control is indicated. Indicators of loss of primary control are flow from the well, an increase in pit volume, or when the drilling fluid used to fill the hole on trips is less than the calculated pipe displacement volume. The emergency signal for well control procedures will be a single long blast of the rig air horn.

Kick While Drilling - Procedures And Responsibilities

Driller:

- 1. Stop the rotary and hoist the kelly above the rotary table.
- 2. Stop the mud pump(s).
- 3. Check for flow.
- 4. If flowing, sound the alarm immediately.
- 5. Ensure that all crew members fill their responsibilities to secure the well.
- 6. Record drill pipe and casing shut-in pressures and pit volume increase and begin kill sheet.

Derrickman:

- 1. Go to BOP/choke manifold area.
- 2. Open choke line valve on BOP.
- 3. Signal to Floorman #1 that the choke line is open.
- 4. Close chokes after annular or pipe rams are closed.
- 5. Record shut-in casing pressure and pit volume increase.
- 6. Report readings and observations to Driller.
- 7. Verify actual mud weight in suction pit and report to Driller.
- 8. Be readily available as required for additional tasks.

Floorman # 1:

- 1. Go to accumulator control station and await signal from Derrickman.
- 2. Close annular preventer and HCR on signal (if available, if not then close pipe rams).
- 3. Record accumulator pressures and check for leaks in the BOP or accumulator system.
- 4. Report to Driller, and be readily available as required for additional tasks.

Floorman # 2:

- 1. Start water on motor exhausts.
- 2. Notify Contractor Tool Pusher or Rig Manager of well control situation.
- 3. Check location for ignition sources and extinguish or turn off, and stop any welding in progress.
- 4. Report to Driller, and be readily available as required for additional tasks.

Floorman # 3:

1. Stand-by with Driller, and be readily available as required for additional tasks.

Tool Pusher/Rig Manager:

- 1. Notify Oxy Representative and report to rig floor.
- 2. Review and verify all pertinent information.
- 3. Communicate information to Oxy Representative, and confer on an action plan.
- 4. Finalize well control worksheets, calculations and preparatory work for action plan.
- 5. Initiate and ensure the action plan is carried out.
- 6. Communicate any changes in well or site conditions, or any indications that the action plan needs to be revised to the Oxy representative.

Oxy Representative:

1. Notify Operation Specialists or Team Leader and RMT Leader or Local Incident Commander, and Police, Fire Department, or other local emergency services as required.

Kick While Tripping - Procedures and Responsibilities

Driller:

- 1. Sound the alarm immediately when pipe displacement volume is less than 75% of calculated.
- 2. Position the upper tool joint just above rotary table and set slips.
- 3. Check for flow.
- 4. Ensure that all crew members fill their responsibilities to secure the well.
- 5. Record drill pipe and casing shut-in pressures and pit volume increase, and begin kill sheets.

Derrickman: (same as while drilling)

Floor Man # 1:

- 1. Install full opening valve (with help from Floorman #2) in top drill string connection.
- 2. Tighten valve with make up tongs.
- 3. Go to accumulator control station and await signal from Derrickman.
- 4. Close annular preventer and HCR valve on signal (if available, if not then close pipe rams).
- 5. Record accumulator pressures and check for leaks in the BOP and accumulator system.
- 6. Report to Driller, and be readily available as required for additional tasks.

Floor Man # 2:

- 1. Assist installing full opening valve in drill string.
- 2. Position back-up tongs for valve make-up.
- 3. Start water on motor exhausts.
- 4. Notify Contractor Tool Pusher or Rig Manager of well control situation.
- 5. Check location for ignition sources and extinguish or turn off, and stop any welding in progress.
- 6. Report to Driller, and be readily available as required for additional tasks.

Floorman # 3, Rig Manager/Tool Pusher, and Oxy Representative: (same as while drilling)

PUBLIC RELATIONS

Oxy recognizes that the news media have a legitimate interest in incidents at Oxy facilities that could affect the public. It is to the company's benefit to cooperate with the news media when incidents occur because these media are our best liaison with the public.

Our objective is to see that all reports of any emergency are factual and represent the company's position fairly and accurately. Cooperation with news media representatives is the most reliable guarantee that this objective will be met.

All contract and Oxy employees are instructed <u>NOT</u> to make any statement to the media concerning the emergency incident. If a media representative contacts any employee, they should refer them to the designated Emergency Command Center where they should contact the Incident Commander or his designated relief for any information concerning the incident.

OXY PERMIAN DOWNHOLE SERVICES GROUP

	LOCATION	OPFICE "	HÔME	CELL	PAGER
Manager Operations S	upport 🔆	and the second second			
Hardesty, Steve	Midland	432-685-5880	432/694-6441	713-560-8095	
Team Leader			Market Printer		
Pennington, Randy	Midland	432-685-5684	432/689-7642	432-556-0207	713-312-8186
 			Toledo Bend =	318-590-2349	
Operations Specialists				12.46	
Fleming, Joe	Midland	432-685-5858	432/699-0875	432-425-6075	432-498-3281
Ray, Fred	Midland	432-685-5683	432/362-2857	432-661-3893	432-499-3432
HES Tech		e film of the market for a large	and party of the p	PLANTE DE T	Dignitus en tra
Thompson, Don	Midland	432-685-5719	432/684-3900	432-556-1505	

Emergency Notification Numbers

Direction of the second of the	ilie Autiherities	
	The second second	And the Committee of th
New Mexico State Police	Artesia	505/746-2704
New Mexico State Police	Carlsbad	505/885-3137
New Mexico State Police	Hobbs	505/392-5588
Eddy County Sheriff's Office	Artesia	505/746-2704
Eddy County Sheriff's Office	Carlsbad	505/887-7551
Lea County Sheriff's Office	Hobbs	505/393-2515
Local Emergency Planning Center	Eddy County	505/887-9511
Local Emergency Planning Center	Lea County	505/397-9231
New Mexico Oil & Gas Commission	Artesia	505/748-1283
New Mexico Oil & Gas Commission	Hobbs	505/393-6161
NM Emergency Response Center	Hobbs	505/827-9222

Emerg	jency Services	
Fire Fighting, Rescue & Ambulance	Artesia	911
Fire Fighting, Rescue & Ambulance	Carlsbad	911
Fire Fighting, Rescue & Ambulance	Hobbs	911
Flight For Life	Lubbock	806/743-9911
Aerocare	Lubbock	806/7478923
Med Flight Air Ambulance	Albuquerque	505/842-4433

Other Er	nergency Services	
Boots and Coots		1/800-256-9688
Cudd Pressure Control	Midland	432/699-0139
B.J. Services	Artesia	505/746-3569
Halliburton	Artesia	505/746-2757

OXY Permian Production and Plant Personnel OXY Permian Crisis Team Hotline Notification (713) 935-7210

PERSON/	LOCATION	OFFICE	FAX	CELL	PAGER
Asset Management-Operations Areas:					
OXY Permian General Manager: Tom Menges	Houston	(281) 552-1147	(281) 552-1484	(713) 560-8038	
South Permian Asset: Matt Hyde	Midland	(432) 685-5802	(432) 685-5930	(432) 556-5016	
RMT/PMT Leaders: South Permian Asset		1 000-0002		000 0010	
Frontier RMT:	Midland				
					e pro-
PERSON	LOCATION IS	OFFICE	FAX	CELL	PAGER
Production Coordinators: S. Permian Asset New Mexico: John Erickson	Hobbs	(505)	(505)	(505)	(505)
	 Y Permian HES Perso		397-2671	390-6426	<u>370-6836</u>
OXY/Permian Crisis	: Team Hotline Notific	alion (743)	35-7210		

PERSON	LOCATION	OFFICE	FAX	OELL.	PAGER
HES Coordinators & Area of Responsibility				0.00	
Frontier:	Midland				
HES Techs & Area of Responsibility	the profession of				terral light
Hobbs RMT:	Hobbs	(505)	(505)	(505)	(877)
Steve Bishop		397-8251	397-8204	390-4784	339-1954- 1118#

OXY USA WTP Limited Partnership

P.O. Box 50250, Midland, TX 79710-0250

March 1, 2005

10: 25

United States Department of the Interior Bureau of Land Management Roswell District Office 2909 West Second Street Roswell, New Mexico 88201

Re: Application for Permit to Drill OXY USA WTP Limited Partnership Elizando A Federal #7 Eddy County, New Mexico Lease No. NM-0354232

Gentlemen:

OXY USA WTP Limited Partnership respectfully requests permission to drill our Elizando A Federal #7 located 1650 FSL and 660 FEL of Section 21, T21S, R27E, Eddy County, New Mexico, Federal Lease No. NM-0354232. The proposed well will be drilled to a TD of approximately 11800' (TVD). The location and work area has been staked. It is approximately 3 miles northeast of Carlsbad, New Mexico.

In accordance with requirements stipulated in Federal Onshore Oil and Gas Order No. 1 under 43 CFR 3162.1, our Application for Permission to Drill and supporting evidence is hereby submitted.

- I. Application for Permit to Drill:
 - 1. Form 3160.3, Application for Permit to Drill.
 - Form C-102 Location and Acreage Dedication Plat certified by Gary G. Eidson, Registered Land Surveyor No. 12641 in the State of New Mexico, dated June 14, 2004.
 - 3. The elevation of the unprepared ground is 3225 feet above sea level.
 - 4. The geologic name of the surface formation is Permian Rustler.
 - 5. Rotary drilling equipment will be utilized to drill the well to TD 11800' (TVD), and run casing. This equipment will then be rigged down and the well will be completed with a pulling unit.
 - 6. Proposed total depth is 11800' TVD.
 - 7. Estimated tops of important geologic markers.

 Wolfcamp
 8700' TVD

 Strawn
 10200' TVD

 Atoka
 10700' TVD

 Morrow
 11000' TVD

8. Estimated depths at which anticipated water, oil, gas or other mineral bearing formations are expected to be encountered:

Primary Objective: Morrow 11000' TVD

Secondary Objective: Atoka 10700' TVD

APD - Elizando A Federal #7 Page 2

The proposed casing program is as follows:

13-3/8" 48# H40 ST&C new casing set at 600' Surface:

Intermediate: 9-5/8" 36# HCK/K55 ST&C new casing from 0-2700'

5-1/2" 17# N80/HP110 LT&C new casing from 0-11800' Production:

HP110-3400' N80-8400'

10. Casing setting depth and cementing program:

> 13-3/8" surface casing set at 600' in 17-1/2" hole. Circulate cement with 360sx HES light premium plus w/ 2% CaCl₂ + .25#/sx Flocele followed by 250sx PP w/ 2% CaCl₂ + .25#/sx Flocele.

If cement does not circulate, a temperature survey will be run to find the TOC and then finish cementing to surface through 1" using Class C with 2% CaCl2.

9-5/8" intermediate casing set at 2700' in 12-1/4" hole. В. Circulate cement with 595sx Interfill C w/ .25#/sx Flocele followed by 200sx PP w/ 2% CaCl₂.

If hole conditions dictate, a DV tool may be run to ensure that the intermediate string is cemented to surface.

If cement does not circulate, a temperature survey will be run to find the TOC and then finish cementing to surface through 1" using Class C with 2% CaCl₂.

Note: Cement volumes may be adjusted according to fluid caliper.

C. 5-1/2" production casing set at 11800' in 8-3/4" hole. Cement with 350sx Interfill H w/ .1% HR-7 followed by 400sx Super H w/ .5% HR-344 + .4% CFR-3 + 5#/sx Gilsonite + 1#/sx salt + .2% HR-7.

Estimated top of cement is 8000'.

Note: Cement volumes may need to be adjusted to hole caliper.

11. Pressure Control Equipment

> 0-600' None

600-2700' 13-3/8" 3M annular preventer, to be used as

divertor only. Exhibit A

2700-11800' 11" 5000# ram type preventers with one set blind

> rams and one set pipe rams and a 5000# annular type preventer. A choke manifold and 120 gallon accumulator with floor and remote operating stations and auxiliary power system. Rotating

head below 8000'. Exhibit A.

APD - Elizando A Federal #7 Page 3

A kelly cock will be installed and maintained in operable condition and a drill string safety valve in the open position will be available on the rig floor.

After setting the 9-5/8" casing, the blowout preventers and related control equipment shall be pressure tested to 5000 psi. Any equipment failing to test satisfactorily shall be repaired or replaced. Results of the BOP test will be recorded in the Driller's Log. The BOP's will be maintained ready for use until drilling operations are completed.

BOP drills will be conducted as necessary to assure that equipment is operational and each crew is properly trained to carry out emergency duties.

Accumulator shall maintain a pressure capacity reserve at all times to provide for the close-open-close sequence of the blind and pipe rams of the hydraulic preventers.

12. Mud Program:

0-600′	Fresh water/native mud. Lime for pH control (9-10). Paper for seepage. Wt.8.7-9.2 ppg, vis 32-34 sec.
600-2700′	Fresh/*brine water. Lime for pH control (10-10.5). Paper for seepage. Wt. 8.3-9.0/10.0-10.1ppg, vis 28-29 sec. *Fresh water will be used unless chlorides in the mud system increase to 20000PPM.
2700-8000′	Fresh water. Lime for pH control (9-9.5). Paper for seepage. Wt. 8.3-8.5 ppg, vis 28-29 sec.
8000-10000′	Cut brine. Lime for pH control $(10-10.5)$. Wt. 9.6-10.0 ppg, vis $28-29$ sec.
10000-11800′	Mud up with an Duo Vis/Flo Trol system. Wt. 9.6-10.0 ppg, Vis 32-36sec, WL<10cc.

Mud system monitoring equipment with derrick floor indicators and visual/audio alarms shall be installed and operative prior to drilling into the Wolfcamp formation. This equipment will remain in use until the production casing is run and cemented. Monitoring equipment shall consist of the following:

- 1) A recording pit level indicator.
- 2) A pit volume totalizer.
- 3) A flowline sensor.

APD - Elizando A Federal #7 Page 4

- 13. Testing, Logging and Coring Program:
 - A. Testing program: No DST's are anticipated.
 - B. Mud logging program: One-man unit from 6000' to TD.
 - C. Electric logging program: CNL/LDT/CAL/GR, DLL/CAL/GR.
 - D. Coring program: Possible sidewall rotary cores.
- 14. No abnormal temperatures, or H2S gas are anticipated. H2S Contingency Plan is attached per NMOCD requirements. The highest anticipated pressure gradient would be .55psi/ft. Adequate flare lines will be installed off the mud/gas separator where gas may be flared safely.
- 15. Anticipated starting date is September 1, 2005. It should take approximately 30 days to drill the well and another 10 days to complete.
- 16. The Multi-Point Surface Use & Operation Plan is attached.
- 17. If the Bureau of Land Management needs additional information to evaluate this application, please advise.

Very truly yours,

David Stewart

Sr. Regulatory Analyst

OXY USA WTP LP

DRS/drs

Attachments



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

June 13, 2005 OXY USA WTP LIMITED Partnership P.O. Box 50250 Midland, TX 79710-0250 Attn: Mr. David Stewart or To Whom It May Concern

RE: APPLICATION FOR PERMIT TO DRILL

ELIZANDO A FEDERAL #7

Section 21, T21S-R27E, 1980' FSL & 660' FEL

EDDY COUNTY, NEW MEXICO

Dear David or To Whom It May Concern,

The application for permit to drill identified above has been filed with this office will need to have the following stipulation (in part) for approval:

OXY USA WTP LIMITED Partnership is to catch mud samples from the flow line in order to determine the chloride content of the drilling mud. Samples are to be taken from @ 600' down to the intermediate casing setting depth of @ 2700'.

Results of these tests are to be submitted to our office and the Bureau of land Management. Thank you for your assistance.

Sincerely,

Bryan G. Arrant PES, District II Artesia NMOCD