Submit 3 Copies To Appropriate District	State of New N	lexico	Form C-103	
Office <u>District I</u>	Energy, Minerals and Natural Resources		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.		
District II 811 South First, Artesia, NM 88210 OIL CONSERVATION DIVIS		N DIVISION	30-005-63509	
District III 1220 South St. France		ancis Dr.	5. Indicate Type of STATE	
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505		STATE X FEE  6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			VA-1834	ius Deuse 110.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEDEN OR DILIG DACK TO		DI LIC DACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:  Oil Well Gas Well X Other		Ten Mile Unit		
1. Type of Well:		123		
Oil Well Gas Well X				
2. Name of Operator		2003	8. Well No.	
10 00 50FHV 60		0 Pool name or Wildoot		
1 st Tradition of Operator		9. Pool name or Wildcat Wildcat Mississippian		
105 5. 4 ··· 511661 Artesi	a, 14/4/ 88210	ARTESIA 70	WINGCOT MISSISSI	ppian
4. Well Location	6/0			
4. Well Location				
Unit Letter <u>G: 1650</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>East</u> line				
Santian 22	T1: 14C D	205	NR Ch.	
Section 33	Township 14S Ran			aves County
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3583' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
		· ·		ALTERING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	ik	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB	ND	
OTHER:			to and atimulate	V
OTHER: Perforate and stimulate  X  Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompilation.				
2/6/03 – Perforate Morrow 8682'-8694' and 8734'-8738' with 9642" holes. Acidize with 1600g 7-1/2% MSA, 1000				
SCF N2/bbl + balls. 2/17/03 – Frac with 32,000g 70Q linear 40# CMHPH/CO2 foam carrying 31,500# 20/40 tempered DC sand.				
2/24/03 – Set 4-1/2" composite plug at 8655'. Perforate Atoka 8549'-8556' with 4242" holes.				
2/26/03 – Acidize Atoka with 700g 7-1/2% MSA + 1000 SCF/bbl N2 + balls.				
3/4/03 – Frac with 33,000g foa			noprop 20/40 sar	nd.
3/6/03 – Drilled out composite plug at 8655'.				
3/12/03 – Set composite plug at 8525'. Perforate Strawn 8424'-8432' with 4842" holes.				
3/13/03 – Acidize Strawn with 800g 7-1/2% IC HCL, 1000 SCF/bbl N2 + balls. 3/18/03 – Perforate Cisco 7711'-7724' with 5242" holes.				
3/20/03 – Periordie Cisco // 11 3/20/03 – Acidize Cisco with 1				2
3/25/03 – Drilled out composit		r at 8344'		
I hereby certify that the information			lge and helief	<del></del>
SIGNATURE				
Type or print name Tina Huerta Telephone No. 505-748-1471				
(This space for State use)	a ch		1 clophone 140	. 500 / 10 14/1
	for second TITLE			APR 0 1 2003
Conditions of approval, if any:	ter lecond TITLE			DATE