Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an				S. Lease Schal No. SL NM02447, BHL NM02447 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
Type of Well				Big Eddy Unit 68294X 8. Well Name and No.	
2. Name of Operator BOPCO, L. P.				Big Eddy Unit #251H	
3a Address	3b. Phone No. (include area code)		9. API Well No. 30-015-40499		
P. O. Box 2760, Midland, TX 79702		432-683-2277		10. Field an	d Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					or Porish State
Surface: SESE, UL P, 620' FS Bottom Hole: 660' FSL, 1155'		W103.851683	11. County or Parish, State Sec 35, T19S, R31E Eddu		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE,	REPORT, OF	ROTHER DATA
TYPE OF SUBMISSION	YPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (S	tart/Resume)	Water Shut-Off
r	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamation Recomplete		Well Integrity Other Variance for 9-5/8"
Subsequent Report	Change Plans	Plug and Abandon	Temporarily A	Abandon	cement job.
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa	1	
cementing operations for temperature survey was r	the 9-5/8" casing string, cemer	nt was not circulated to cement and the cement	surface on the secon top was located at	ond stage. See 40' RKB or 10	b below ground level. BOPCO,
riance for 10	Accepted for NMOC	record D S S S S S S S S S S S S S S S S S S	ν	ECEIV EC 1 2 20 OCD ART	012
14. Thereby certify that the fore Name (Printed/Typed)					
Charles Warne	· · · · · · · · · · · · · · · · · · ·	Title D	rilling Engineer		· · · · · · · · · · · · · · · · · · ·
Signature Soulur L	Lane	Date	10-4-12		APPROVED
	THIS SPACE FOR I	EDERAL OR S	TATE OFFICE	USE r	- TITIO V LU
Approved by Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant to	or equitable title to those rights in conduct operations thereon.	does not warrant or n the subject lease	itle	BIL	Date DEC 1 1 2012 LIMMON MANAGEMENT
Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudul	e 43 U.S.C. Section 1212, make it a ent statements or representations	crime for any person kn as to any matter within its	owingly and willfully jurisdiction.	to make to any	CARLOGIAD AGENCY OF THE LOCATION OF THE LOCATI
/1					

9-5/8" Cement Details

A DV tool and external casing packer were run on the 9-5/8" casing string at 2710' and 2713' respectively. The 13-3/8" casing was set at 2667' and the top of the Capitan Reef was called due to loss circulation at 2790'. Prior to running casing, a 3-arm wireline caliper was run to help determine ECP placement as well as cement volumes. In addition to this, the 50' minimum distance from previous casing point and casing tally were factors used in selecting the ECP placement. Therefore, the 2710' DV tool placement was the best available setting depth.

Cement 1st stage of 9-5/8" intermediate casing. Pump 10 bbls FW spacer, 40 bbls of WG-19 Gel w/red dye followed by lead cement of 1100 sx (335 bbls) of Class C + additives (13.6ppg, 1.71 cu ft/sk yield) Displaced with 315 bbls FW. Final circulating pressure 1100 psi. Bumped plug @ 315 bbls with 500 psi over at 4:15 PM CST on 9/26/12. Released pressure and bled back 2 bbls - floats held. The DV tool was opened with 760 psi. Circulated 60 barrels (197 sacks) of cement to half pit.

Cement 2nd stage of 9-5/8" intermediate casing. Pump 20 bbls FW followed by lead cement of 560 sx (184 bbls) of EconoCem - HLC (12.7 ppg, 1.85 cu ft/sk yield) followed by 100 sx (23 bbls) of tail cement Class C + additives (14.8 ppg, 1.33 cu ft/sk yield). Displaced with 205 bbls FW. Bumped plug and closed DV tool with 1930 psi (1179 psi over). Released pressure and bled back 1 bbl - tool closed. Did not circulate cement to surface but did get red dye back to surface.

A temperature survey was run and found TOC at 40'.