


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

njmw 1303854425 OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Mobil Federal Battery	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		Lease No.	

30-015-20751

LOCATION OF RELEASE								
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	29	23S	31E	1980	South	1980	East	Eddy

Latitude N 32.27321° Longitude W 103.79784°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	60 bbls oil, 20 bbls water	Volume Recovered	0 bbls
Source of Release	Tank overflow caused by vapor-locked transfer pump	Date and Hour of Occurrence	1/14/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD; James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	1/14/13 @ 10:06 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The South water transfer pump vapor-locked causing a tank to overflow and spill 60 bbls of oil and 20 bbls of water onto the ground. 0 bbls were recovered and the pump was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 55' x 55'. The south water transfer pump vapor-locked causing a tank to overflow and spill 60 bbls of oil and 20 bbls of water onto the ground. 0 bbls were recovered and the pump was repaired. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by District Supervisor	Signed By:
Title: HES Specialist	Approval Date: FEB 07 2013	Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-4-13 Phone: (575) 397-8216	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

2RP-1545

March 7th 2013

* Attach Additional Sheets If Necessary