

	Submit 1 Copy To Appropriate District State of New Met		_	Form C-103	
	District 1 – (575) 393-6161 Energy, Minerals and Natur 1625 N. French Dr., Hobbs, NM 88240			Revised August 1, 2011 WELL API NO.	
	rict II – (575) 748-1283 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION		30-015-20482		
	11 S. First St., Artesia, NM 88210       OIL CONSERVATION DIVISION         District III - (505) 334-6178       1220 South St. Francis Dr.		5. Indicate Type of Leas		
	1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease	FEE	
	District IV – (505) 476-3460 Salita Fe, 1NIVI 87 1220 S. St. Francis Dr., Santa Fe, NM 87505	505	6. State OII & Gas Lease	e INO.	
	SUNDRY NOTICES AND REPORTS ON WELLS	· · · · · · · · · · · · · · · · · · ·	7. Lease Name or Unit A	Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well S Gas Well S Other		Jackson Estate BY	-8	
			8. Well Number	· · · ·	
			4		
	2. Name of Operator	9. OGRID Number			
	2. Name of Operator Yates Petroleum Corporation		025575		
	3. Address of Operator		10. Pool name or Wildcat		
	105 South Fourth Street, Artesia, NM 88210		Eagle Creek; San Andres		
	4. Well Location	· · ·			
	Unit Letter <u>E</u> : 2310 feet from the North	line and	990 feet from the	Westline	
	Section 22 Township 17S Ran	ige 25E	NMPM Eddy	County	
	11. Elevation (Show whether DR,				
	3538'		and the second		
	· · · · · · · · · · · · · · · · · · ·				
	12. Check Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data		
	NOTICE OF INTENTION TO:	SUE	SEQUENT REPOR		
	PERFORM REMEDIAL WORK D PLUG AND ABANDON	REMEDIAL WOR			
		CASING/CEMEN			
	DOWNHOLE COMMINGLE	ON ON TO OPENNEN			
	OTHER:	OTHER:			
	13. Describe proposed or completed operations. (Clearly state all p				
	of starting any proposed work). SEE RULE 19 15.7.14 NMAC	. For Multiple Co	ompletions: Attach wellbor	e diagram of	
	proposed completion or recompletion.				
Yates Petroleum Corporation plans to plug and abandon this well as follows:					
	1. NU BOP. TOH with production equipment.				
	2. RIH with bit and scraper across perfs at 1520' and circulate Class "C				
	unable to get across perfs then TOH and TIH with a CIBP and set above				
	3. Cut off wellhead and verify that there is cement behind all casing stri RU wireline unit, perforate and circulate cement to surface behind each of				
	casing.	casing sumg beror	e cementing to surface mak	ic production	
	A T ( 1) does had a wondern and allow have the	nted providing wor	ł		
	Appival Old	inted providing wor	j13 Da		
	Wellbore schematics attached IS complete a	vlune 18-de	MECEN	1	
		•		EDT	
	NOTE: Yates Petroleum Corporation will use steel pits and no earth pit	S	MAR 1 4 20	112	
	······		NMOCD ARTE	13	
	Spud Date: Rig Release Da	te:	ARTE		
		L		SIA /	
	I hereby certify that the information above is true and complete to the be	st of my knowledg	ge and belief.		
	A Mit to	1			
	SIGNATURE (Charles) TITLE Regu	llatory Reporting S	SupervisorDATEMar	<u>cn 13, 2013</u>	
	Type or print name <u>Tina Huerta</u> E-mail address: <u>tin</u>	ah@yatespetroleu	m.com PHONE: 5	575-748-4168	
	For State Use Only				
	RPIrda D.				
Δ	APPROVED BY: RADIOL TITLE D-50 Conditions of Approval (if any): SEE 14thAbed COA'S	- J. Sypla	DATE DATE	Nen 18 2013	
Ø	Conditions of Approval (if any): SEE Athered COA'S	,			
/					



Size/Wt/Grade	Depth Set
10 ¾" 40# K-55	505'
7" 20# & 23# K-55	1,144'
4 ½" 11# & 5 ½" 14# K-55	1,534`
	<u> </u>



## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## **CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT**

Operator: Lates Pet. Corp Well Name & Number: Aackson Estate BY #4 API #: 30-015-20482

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: March 18 - 2013

APPROVED BY: ADde

## **GUIDELINES FOR PLUGGING AND ABANDONMENT**

## DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o **Devonian**
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
  must be cut and pulled with plugs set at these depths or casing must be perforated and cement
  squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
   Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).