Form 3160-5 (April 2004)

1. Type of W

3a. Address

Oil Well.

2. Name of Operator OXY USA Inc.

P.O. Box 50250 Midland, TX 79710

determined that the site is ready for final inspection.)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

16696

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Other

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Gas Well(

NANMELSE (e)
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No.
Cedan Canyon 22 # 1 #
9. API Well No.
30-015-40665

10. Field and Pool, or Exploratory Area

4. Location of Well <i>(Footage, Sec., 1</i> 5 · 1960 FS4 1960 F	T., R., M., or Survey Description, FWL WESW(K)	sec as Tays	, R29E	11. County of)vaw Bove Sp r Parish, State	ring		
-2012 FSL 9871				Egg	~ WM			
12. CHECK AF	PROPRIATE BOX(ES) T	O INDICATE NATURI	E OF NOTICE, R	EPORT, OR	OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Statement of Statement of Statem	· -0.	Water Shut-Off Well Integrity Other Corrole	tion		
13 Describe Proposed or Complete	ed Operation (clearly state all no	tinent details including estin	nated starting date of ar	ny nronosed wor	k and approximate duration	thereof		

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

3b. Phone No. (include area code)

432-685-5717

RUPU 12/6/12, Drill and clean out to PBTD @ 11770'. Pressure test csg to 6250', held for 30min, tested good. 12/12/12. 1/22/13, Perf @ 11692-11000, 10772-10080, 9852-9160, 8932-8240' Total 136 holes. Frac w/ 67949g Treated Wtr + 16000g 15% HCL acid + 88521g Waterfrac GR15 + 653812g Hybor GR15 w/ 1339800# sand, RD HES. RIH w/ 2-7/8" tbg w/ pkr @ 7100', swab, flow back to clean up well and test well for potential.

<u> </u>									
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)									
David Stewart		Title Regulatory Advisor							
Signature da Ser	Date	3/26(EDTEN	EAD DE	CODD			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE-1 TED TON TILLUTION									
Approved by		Title		Date A PR	C 0010	·			
Conditions of approval, if any, are attached. Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject I which would entitle the applicant to conduct operations thereon.	ease	Office		2 an	0 2013				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for an States any false, fictitious or fraudulent statements or representations as to any matter.	y person er withir	knowingly and will its jurisdiction.	fully to mial	etollan), debañ CARLSRAD	inightlyitagencyEp FIELD OFFICI	of the United			
(Instructions on page 2)						-			