OCD Artesia

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5.	Lease Serial No.
	NMNM53219

SUNDRY I Do not use thi abandoned wel	NMNM53219 6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRII	7. If Unit or CA/Agreement, Name and/or No. NMNM112743					
Type of Well Oil Well	Well Name and No. WHITBREAD BFG FEDERAL COM 1					
Name of Operator YATES PETROLEUM CORPO	9. API Well No. 30-015-33932-00-S2					
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	(include area co 8-4168 3-4585			Exploratory		
4. Location of Well (Footage, Sec., T. Sec 1 T22S R24E SWNW 198		RECEIVED			11. County or Parish, a	
12 CHECK APPR	OPRIATE BOY/ES	MAY 08		F NOTICE DI	EPORT OR OTHER	P DATA
	ROPRIATE BOX(ES	ANACE AR	r come destrict H II		Croki, ok omisi	CDATA .
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	□ Dee			ion (Start/Resume)	□ Water Shut-Off
Subsequent Report ■	☐ Alter Casing	_	ture Treat	☐ Reclam		☐ Well Integrity
	□ Casing Repair□ Change Plans	_	Construction and Abandon	☐ Recomp		☐ Other
☐ Final Abandonment Notice	- •		Back	☐ Water I	arily Abandon	
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab- determined that the site is ready for fi 3/26/13 - NU BOP. Released 3/27/13 - Set a 7 inch CIBP at loose. 3/28/13 - Tagged up at 3556 f	ally or recomplete horizont ick will be performed or pro- operations. If the operation andonment Notices shall to inal inspection.) packer. 3556 ft. Pumped and t. Fell out and pushed	ally, give subsurface wide the Bond No. or on results in a multiple filed only after all diplomater all diplomater by the bold	locations and mentile with BLM/I ecompletion or requirements, incompleted of the control of the	asured and true ve BIA. Required sul ecompletion in a r luding reclamation	ertical depths of all pertin beequent reports shall be new interval, a Form 316 n, have been completed, a	ent markers and zones. filed within 30 days 0-4 shall be filed once
	Pumped 200 bbls moles at 3420 ft. Broke at 3257 ft. Perforated uld not pump into. Sp 535 ft. Need to be 50	ud. Dug up cella circulation up su at 1610 ft. Pum potted 30 sx Clas oft above 9-5/8 ir	ped 6 bbls downs C cement at characteristics.	wn tubing. 1660 ft. W Ø @ spotted 25 s _X ;		ing of the well hors.
14. I hereby certify that the foregoing is Comm Name (Printed/Typed) TINA HUE	Electronic Submission For YATES PE itted to AFMSS for pro-	TROLEUM CORP	ORÁTION, sen NY DICKERSO	it to the Carlsba N on 04/24/2013	ad	
Signature (Electronic S	Date 04/23	3/2013				
	THIS SPACE	FOR FEDERA			SE	
Approved By ACCEPT		JAMES A AMOS TitleSUPERVISOR EPS Date 05/05/2013				
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the conductive the applicant to conduct the applicant	uitable title to those rights		Office Carlsl	pad		
Title 18 LLS C. Section 1001 and Title 42	ILCC Section 1212 male	a it a arima for arrest	room lemonnin -1-	and will 6.11+	alea ta anno dannotos contra	

Fitle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Additional data for EC transaction #205169 that would not fit on the form

32. Additional remarks, continued

4/4/13 - Tagged cement plug at 1415 ft. Perforated 4 holes at 150'. Circulated 50 sx Class C cement to surface.
4/17/13 - Dug out cellar and cut off wellhead. Filled 20 inch casing with cement. BLM was

observing and was on location when cement was originally pumped 4/4/13, watched fill up and was ok with it. Prepare to install dry hole marker. Filled cellar.

4/18/13 - Received call from Basic welder that during cut and cap, backside was not topped off with cement. Received call from Basic welder that during cut and cap, backside was not topped off with cement. Pron to finish installing development. to surface. Prep to finish installing dry hole marker.
4/18/13 - Installed dry hole marker. WELL IS PLUGGED AND ABANDONED.