Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135

BUREAU OF LAND MANAGEMENT	MAY 3 1 - 3 1113	L_	Expires: July 31, 2010
SUNDRY NOTICES AND REPORTS ON WELL Do not use this form for proposals to drill or to re-en	SMOCD ARTES	5.	Lease Serial No. NMNM104667
abandoned well. Use form 3160-3 (APD) for such pro	posals.	6	If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on rever	se side	7.	If Unit or CA/Agreement, Name and/or No.

Do not use thi abandoned we	is form for proposals to di II. Use form 3160-3 (APD)	rill or to re-anter ah C for such proposals.	D ARTESI	6. If Indian, Allottee o	r Tribe Name	
SUBMIT IN TRI	PLICATE - Other instruction	ons on reverse side.		7. If Unit or CA/Agree	ement, Name and	or No.
1. Type of Well Oil Well Gas Well Oth	ier			8. Well Name and No. TUNA 28 FEDER	AL 1	
Name of Operator COG OPERATING LLC	Contact: Bf E-Mail: bmaiorino@c	RIAN MAIORINO oncho.com		9. API Well No. 30-015-37645		
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	W. ILLINOIS AVE	b. Phone No. (include area co Ph: 432-221-0467	ode)	10. Field and Pool, or BONE SPRING	Exploratory	
4. Location of Well (Footage, Sec., T	, R., M., or Survey Description)			11. County or Parish, a	and State	
Sec 28 T26S R25E NENE 130	00FNL 660FEL			EDDY COUNTY, NM		
12. СНЕСК АРРГ	ROPRIATE BOX(ES) TO I	NDICATE NATURE C	F NOTICE, RE	PORT, OR OTHEI	R DATA	
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION			
Notice of Intent	☐ Acidize	Deepen	□ Production	on (Start/Resume)	■ Water Shu	ıt-Off
	Notice of Intent		□ Reclamat		☐ Well Integ	grity
☐ Subsequent Report	□ Casing Repair	☐ New Construction			☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon☐ Plug Back	□ Tempora□ Water Di	rily Abandon		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fit COG Operating LLC respectful	k will be performed or provide the operations. If the operation result that the control of the c	e Bond No. on file with BLM/ is in a multiple completion or only after all requirements, in-	BIA. Required substrecompletion in a necluding reclamation, the Tuna 28 Fec	sequent reports shall be aw interval, a Form 316, have been completed, a deral #1	filed within 30 da 0-4 shall be filed and the operator b	ays once
Test anchors if necessary MIRU Kill well if necessary. Install back pressure valve. Remove wellhead & install BC	q.	Acc	epted for rec	SUBJECT T COAPPROVAL	BY STAT	Œ
Attempt to release from on/off cut off)	tool. (If cannot release, pur		necessary,	109/	808	
Pull tubing and visually inspec TIH with tubing open ended	i. II necessary, utilize work	string		EE ATTACHE	D FOR	OVAL
14. I hereby certify that the foregoing is Name(Printed/Typed) BRIAN MA	Electronic Submission #200 For COG OPE Committed to AFMSS for pro	ERATING LLC, sent to the ocessing by JOHNNY DIC	Well Information e Carlsbad	System 0/2013 ()	<u> </u>	UVAL
Signature (Electronic S	lubmission)	Date 05/0	9/2013	APPROVE	ED]	
	THIS SPACE FOR	FEDERAL OR STAT	TE OFFICE US	E		
Approved By		Title		MAY 2 4 20	13 Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	iitable title to those rights in the su		BUR	AU OF LAND MANA CARLSBAD FIELD OF	GEMENT	1
Citie 19 H.C.C. Spation 1001 and Title 42	U.S.C. Sontian 1010 male it	G	d::11611	, v	C.I. I.I.	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #206913 that would not fit on the form

32. Additional remarks, continued

Spot Class H cement mixed at 16.4# gal from 9300 ? 9500 (Morrow top @ 9408?)

Circulate well clean

Spot Class H cement mixed at 16.4# gal from 7600 ? 7800 (Wolfcamp top @ 7525? but bottom Bone Spring perf @ 7505?)
Circulate well clean & TOH

Pressure test casing to 6500 psi
Perforate 3rd Bone Spring @ 7505? (16 holes), 7411? (16 holes) and 7352? (10 holes) and 7306? (10 holes) w/6 spf, 600 phasing utilizing Halliburton cased hole log dated 6/21/10.

TIH w/tubing & packer. Spot acid across perfs. Set packer at 7250?

Acidize zone with 3000 gallons 15% HCl at 3 ? 5 BPM while dropping balls

Shut-in 1 hour & flow back

Pull tubing and packer

Set frac valve & prepare for frac.
Frac well utilizing attached procedure.

Set flow through composit plug at 6700?

Perforate Charkey Sand @ 6865? (14 holes), 6775? (16 holes) and 6716? (10 holes) and 6664? (12 holes) w/6 spf, 600 phasing utilizing Halliburton cased hole log dated 6/21/10.

Frac well utilizing attached procedure.

Set flow through composit plug at 6300? Perforate 2nd Bone Spring @ 6206? (16 holes), 6130? (16 holes), 6057? (10 holes), and 6003? (10 holes) w/6 spf, 600 phasing utilizing Halliburton cased hole log dated 6/21/10.

Frac well utilizing attached procedure.

Set flow through composit plug at 5710?

Perforate 1st Bone Spring @ 5614? (16 holes), -5556? (10 holes), 5502? (10 holes), and 5449? (14 holes) w/6 spf, 600 phasing utilizing Halliburton cased hole log dated 6/21/10.

Frac well utilizing attached procedure.

Shut-in well for 24 hours

Flow well back until dead.


TIH with tubing and drill out plugs. TOH TIH with tubing & gas lift equipment.

Place well on test

Author:	Stroup		
Well Name	Tuna 28 Fed	Well No	#1
Field	Milepost	API#.	30-015-37645
County	Eddy	Prop#	
State	New Mexico	Zone.	Morrow
Date	4/15/2013		
GL	3680'		
KB	3697'		

Description	O.D	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8_	H40	48	279	360	Surface
Inter Csg	9 5/8	J55	_36_	1 220	550	Surface
Prod Csg	7	P110	23	9,962	1,475	Surface
Liner						

Current Well Bore



17 1/2" hole

13-3/8" (H40 - 48#) @ 279' w/360 sx TOC @ surface

2-3/8" N80 Tbg - 339 jts

12 1/4" hole

9-5/8" (J55 - 36#) @ 1220' w/550 sx TOC @ surface

DV Tool @ 3003' w/500 sx

Short Joint @ 6572'

DV Tool @ 6985' w/550 sx

298 jts 2 3/8" L80

7" 10K AS1-X Packer w/on/off tool @ 9566' 1 81 R Niplie @ 9585'

Morrow

9680-82, 9686-95, 9698-9700

8 3/4" hole

7" (P110 - 23#) @ 9962' w/425 sx TOC @ Surface

TD @ 10000'

Author:	Stroup			
Well Name	Tuna 28 Fed	Well No.	#1	
Field	Milepost	API #:	30-015-37645	
County	Eddy	Prop #:		
State	New Mexico	Zone:	Bone Spring	
Date	4/15/2013			
GL	3680'			
KB	3697'			

Description	O.D.	Grade	Weight	Depth	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48	279	360	Surface
Inter Csg	9 5/8	J55	36	1,220	550	Surface
Prod Csg	7	P110	23	9,962	1,475	Surface
Liner						

TD @ 10000'

Proposed Well Bore

17 1/2" hole 13-3/8" (H40 - 48#) @ 279' w/360 sx TOC @ surface

2-3/8" N80 Tbg

12 1/4" hole

9-5/8" (J55 - 36#) @ 1220' w/550 sx TOC @ surface

DV Tool @ 3003' w/500 sx

Short Joint @ 6572'

DV Tool @ 6985' w/550 sx

1st Bone Spring: 5449, 5502, 5556, 5614

2nd Bone Spring: 6003, 6057, 6130, 6206

Bone Spring Charkey Sand: 6664, 6716, 6775, 6865

3rd Bone Spring: 7306, 7352, 7411, 7505

Wolfcamp cement plug: 7600-7800

Cement plug 9300-9500 Morrow 9680-82, 9686-95, 9698-9700

8 3/4" hole

7" (P110 - 23#) @ 9962' w/425 sx TOC @ Surface

Tuna 28 Federal 1 30-015-37645 COG Operating LLC May 24, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 24, 2013.

.

- 1. The operator shall place CIBP at 9630'. Place a balanced cement class H plug from 9630'-9358'. Tag required.
- 2. The operator shall place a balance neat class H cement plug from 7750'-7550. As this plug will not properly seal the Wolfcamp formation according to BLM standards, additional cement must be placed on top during final abandonment.
- 3. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure.
- 4. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

10. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include new well plat and well bore schematic of current well condition when work is complete.

JAM 052413