

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED  
OMB No. 1004-0137  
Expires: October 31, 2014

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

5. Lease Serial No.  
NM000503

6. If Indian, Allottee or Tribe Name

**SUBMIT IN TRIPLICATE – Other instructions on page 2.**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Devon Energy Production Company, L.P.

3a. Address  
333 W. Sheridan Avenue  
Oklahoma City, Oklahoma 73102

3b. Phone No. (include area code)  
405-228-4248

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.  
Cotton Draw Unit 162H

9. API Well No.  
30-015-39730

10. Field and Pool or Exploratory Area  
Cotton Draw; Delaware South

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 860' FWL, Unit M, Sec 11, T25S-R31E

11. County or Parish, State  
Eddy, NM

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA**

**TYPE OF SUBMISSION**

**TYPE OF ACTION**

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other Comp Report

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

*ADade 6/20/2013*  
Accepted for record  
NMOC

12/10/2012 – 02/06/2013

MIRU. Tested Csg to 4500 psi. OK. Ran CBL logs. Found TOC @ 4866'. Perforate Delaware (Brushy Canyon) 8,614 – 12,525'; 180 holes. Frac'd from 8,614 – 12,525' in 6 stages. Frac Totals: 9118 gals 7.5% HCL acid, 107,066 gals Slick wtr, 55,007# 100 Mesh sd, 1,399,836 # 20/40 white sd, 429,261 # SLC sd. RIH w/2 7/8" tubing. EOT @ 8210'. Turn well over to production.

**RECEIVED**

**JUN 12 2013**

**NMOCD ARTESIA**

**ACCEPTED FOR RECORD**

**JUN 8 2013**

*[Signature]*  
**BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE**

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Patti Riechers

Title Regulatory Specialist

Signature

*Patti Riechers*

Date 05/21/2013

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)