

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

RECEIVED

OIL CONSERVATION DIVISION

JUN 26 2013

HOBBSON

220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-02904

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Cave Pool Unit

8. Well Number #26

9. OGRID Number
14070

10. Pool name or Wildcat
G. Jackson 7RVS QN GB SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
State of New Mexico formerly Marks And Garner

3. Address of Operator
811 S. First Street Artesia, NM 88210

4. Well Location

Unit Letter O: 660 feet from the South line and 1980 feet from the East line
Section 5 Township 17S Range 29E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/7/2013 MIRU and lay down rods.

5/8/2013 Changed out wellhead and installed BOP. POOH with tubing and made scrapper run.

5/9/2013 Set CIBP @ 2305'. Circ hole with mud and spotted 25 sx on CIBP. POOH to 1950 and spotted 100 sx cement. WOC and tagged at 998'. Spotted 75 sx @ 998' and SION.

5/10/2013 RIH and tagged at 299'. Circulated cement to surface with 35 sx. Installed marker and cut off anchors.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: [Signature] TITLE DET MGR DATE 6-26-2013

Conditions of Approval (if any):

JUN 26 2013