Submit 1 Copy To Office	Appropriate District	State of New Mexico		Form C-103		
District I – (575) 393-6161 Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION District III – (57) 334-6178 HILE (55) 334-6178				Revised August 1, 2011 WELL API NO.		
				30-015-24991	·	
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 JUN 2 $\stackrel{\circ}{6}$ 201 $\stackrel{\circ}{3}$ 220 South St. Francis Dr. Santa Fe. NM 87505				5. Indicate Type of Lease STATE X FEE		
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NNTOBBSOCD 87505				6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name Red Twelve State		
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other				8. Well Number		
2. Name of Operator State of New Mexico formerly Marks And Garner				9. OGRID Number 14070		
3. Address of Operator				10. Pool name or Wildcat		
811 S. First Street       Artesia, NM 88210       GB Jackson SA Q         4. Well Location       GB Jackson SA Q						
Unit L		et from theSouth	line and	_2310feet from	theEastline	
Sectio		ownship 17S	Range 29E		Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOE					PANDA X	
DOWNHOLE (			CASING/CEMENT			
OTHER:			OTHER:			
of start	be proposed or completed operation ing any proposed work). SEE RU ed completion or recompletion.	ns. (Clearly state all j LE 19.15.7.14 NMAC	pertinent details, and C. For Multiple Cor	d give pertinent dates, npletions: Attach we	, including estimated date llbore diagram of	
5/21/2013	MIRU and started blowing well down. Worked on getting wellhead off.					
5/22/2013	Installed BOP and worked packer loose. POOH with tubing and set CIBP at 2904'.					
5/23/2013	Circulated hole with mud and spotted 25 sx cement on CIBP. POOH to 1806' and spotted 25 sx cement. Picked up packer and isolated small hole above 300'. Laid down packer.					
A/24/2013 RIH to 409' and circulated cement to surface. Cut off wellhead and installed marker.						
Spud Date:	· · · ·	Rig Release Da	ate:			
L.						
I hereby certify	that the information above is true a	and complete to the be	est of my knowledge	e and belief.		
					. •	
SIGNATURE_		TITLE	1 1 <u>0</u> 1 + 4	DAT	Е	
Type or print na	A	E-mail address	S:	РНО	NE:	
For State Use C	4/~ /	ρ.	= times =		1 21 2010	
APPROVED BY Conditions of Approval (if any):						
				J	UN 26 2013	