Thrmit 3 Copies To Appropriate District	State of New Mexico		Form C-103 June 19, 2008	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210			30-015-39239  5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE S FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sainta PC, INIVI 67	303	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name SHRIKE 10 STATE COM	
1. Type of Well: Oil Well Gas Well Other			8. Well Number #2H	
2. Name of Operator LRE OPERATING, LLC.			9. OGRID Number 281994	
3. Address of Operator c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401			10. Pool name or Wildcat: Willow Lake, Delaware SW (96855)	
4. Well Location				
Unit Letter N : 400 feet from the SOUTH line and 2490 feet from the WEST line				
Section 10 Township 25-S Range 28-E NMPM Eddy County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	2923' GL			
12. Check A	ppropriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR			<del></del>	
TEMPORARILY ABANDON				
DOWNHOLE COMMINGLE	_		_	
OTHER: P&A		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
LRE OPERATING, LLC would like	to P&A this well as follows: MIR	USU. TOH w/all pr	roduction equipment. TIH w/tbg to	
LRE OPERATING, LLC would like to P&A this well as follows: MIRUSU. TOH w/all production equipment. TIH w/tbg to ~MD6750'. Circ hole w/P&A mud (25 sx gel/100 bbls water). TOH. Plug #1, (4470'-4370') Delaware Horizontal Lateral w/frac				
ports @ MD5031'-6748'. Set 7" CIBP @ 4470' & top w/25 sx cmt (~133'). WOC. Plug #2 (650'-550'), 9-5/8" csg shoe @ 600'. Perf 3 SQ holes @ 650'. Set 7" PKR @ 400'. Establish rate into SQ holes w/bradenhead valve open. Mix 44 sx cmt & SQ 25 sx outside 7"				
csg & leave 19 sx inside csg. WOC. Tag cmt. Plug #3 (60'-Surface). Perf 3 SQ holes @ 60'. Establish circ out bradenhead w/water.				
with government specs. RD move of			nge. Install P&A marker with cmt to comply	
All cmt calc outside of csg are @ 200	)%.			
Spud Date: 7/28/11	Drilling Rig I	Release Date:		
I hereby certify that the information a			e and belief.	
SIGNATURE Mila	Figgin TITLE Petrole	eum Engineer - Age	nt DATE <u>6/25/13</u>	
Type or print name Mike Pippin	E-mail address:	mike@pippinll	c.com PHONE: <u>505-327-4573</u>	
For State Use Only		- HS 0	and abbase	
APPROVED BY: // // /	TITLE L)	ST Aller	2015 () DATE 7/2013	
Conditions of Approval (if any): CONDITIONS OF APPROVAL ATTACHE	D Approved for plugging of		,	
	Liability under bond is ret	ained pending receipt	RECEIVED	
Approval Granted providing work in Completed by \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	which may be found at OC	D Web Page under	JUN <b>27</b> 2013	
Auly 2.20	Forms, www.cmnrd.state.n	m.us/ocd.		
SEE Attached COA'S				



TOC @ 2185'

TEMP SURVEY

KOP @ 4,470'

# PROPOSED P&A 6/25/13

PLUG #3: 60'-Surface PERF 3 SQ HOLES @ 60' Circ. ~21 sx CMT

9-5/8", 36#, J-55, ST&C Casing @ 600'

Shrike 10 State Com #2H

Sec 10-25S-28E (N)

SHL: 400' FNL, 2,590' FWL BHL: 400' FNL, 330' FWL

Elevation: 2,923' GL

2.938.5' KB

**Eddy County, NM** 

PLUG #2: 650'-550' -- PERF 3 SQ HOLES @ 650' SQ W/44 sx CMT

Surface Cement Information: (200% excess - TOC - Surface)

**Lead** – 150 sacks of 35:65 (Poz:C) + 6% Bentonite + 2% CaCl2 + 0.25 pps Poly-E-Flake

(Density – 12.70 ppg, Yield – 1.88 cuft/sk, Mix Water – 10.07 gps)

Tail - 140 sacks of Class C + 2% CaCl2

(Density – 14.80 ppg, Yield – 1.34 cuft/sk, Mix Water – 6.36 aps)

**Ball-Actuated** 

Frac Port

Liner Top Packer	4,627'
Hydraulic Packer	4,850'
7" Shoe	4,910'
Frac Port -1	5,100'
Hydraulic Packer	5,200'
Frac Port - 2	5,300'
Hydraulic Packer	5,400'
Frac Port - 3	5,500'
Hydraulic Packer	5,600'
Frac Port - 4	5,700'
Hydraulic Packer	5,800'
Frac Port - 5	5,900'
Hydraulic Packer	6,000'
Frac Port - 6	6,100'
Hydraulic Packer	6,200'
Frac Port - 7	6,300'
Hydraulic Packer	6,400'
Frac Port - 8	6,500'
Hydraulic Packer	6,600'
Hydraulic Port	6,694'
TD	6,827'

PLUG #1: 4470'-4370' 7" CIBP @ 4470' #OPPED W/25 sx CMT

6-1/8" Cherry Canyon 6 Lateral

MTD @ 6,827' Est TVD @ 4,776'

Hydraulic Packers

4-1/2"; 11.6#, P110, LTC Liner from 4,627' to 6,827' w/ External Packers & Frac Ports


7"; 23# N-80, LTC Casing @ 4,870' MD (4,787' TVD) @ 65.98 deg inclination

Intermediate Cement Information: (100% excess)

Lead – 250 sacks of 35:65 (Poz:C) + 6% Bentonite + 5% (BWOW) NaCl2 + 0.25 pps Poly-E-Flake (Density – 12.40 ppg, Yield – 2.09 cuft/sk, Mix Water – 11.64 gps) – Top of cement – 1500'

Tail - 160 sacks of Class C + adds.

(Density - 14.80 ppg, Yield - 1.33 cuft/sk, Mix Water - 6.28 gps) - 1247 linear ft of tail cement



# NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

### CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: LRE Operating, LLC
Well Name & Number: Shrike 10 State Com 2H
API #: 30-015-39239

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: July 2, 2013

APPROVED BY:

### GUIDELINES FOR PLUGGING AND ABANDONMENT

### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).