District 1 1625 N. French Dr., Hobbs, NM 88240 1625 N. French Dr., Hobbs, NM 86240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

. ....

State of New Mexico RECEIVED Energy Minerals and Natural Resources
JUN 2 1 2013

Oil Conservation Division

1220 South St. Francis PIMOCD ARTESIA Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action								
NAW 1318334952	(	OPERAT	ror		🛭 Initi	al Report		Final Repor
Name of Company COG OPERATING LLC 229/37   Contact Pat Ellis								
Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077								
Facility Name SRO SWD #101 Facility Type SWD								
Surface Owner STATE Mineral Owner Lease No. (API#) 30-015-26105								
LOCATION OF RELEASE								
Unit Letter Section Township Range Feet from the N G 05 26S 28E	lorth/So	th/South Line   Feet from the   East/West Line   County   EDDY						
Latitude 32.07351 Longitude 104.1067								
NATURE OF RELEASE								
Type of Release Produced water		Volume of	Release 100bbls		Volume Recovered Obbls			
Source of Release Victaulic coupling						d Hour of Discovery 2013 4:00pm		
Was Immediate Notice Given?		If YES, To			00 00 00	13 1.001		
☐ Yes ☐ No ☐ Not Requi	ired		М	ike Brat	cher - NM	IOCD		
By Whom? Michelle Mullins			our 06-12-2013					
Was a Watercourse Reached?	- 1	If YES, Volume Impacting the Watercourse.						
Yes 🛭 No								
If a Watercourse was Impacted, Describe Fully.*								
Describe Cause of Problem and Remedial Action Taken.*								
Describe Classe of Frontin and Religion Action Faken.								
A Victaulic coupling failed causing the release of 100bbls of produced water. The Victaulic coupling has been replaced and the line is back in service.								
Describe Area Affected and Cleanup Action Taken.*								
Initially an estimated 100bbls of produced water was released due to a Victaulic clamp that failed. We were unable to recover any fluid. The spill area is								
located in the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.								
the thirded tot approval prior to any significant tenediation work.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and								
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger								
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other								
federal, state, or local laws and/or regulations.				.,		,		
		OIL CONSERVATION DIVISION						
Signature:		,						
	An	nroyed by f	Nietriat Suparvica	- 100	<u></u>	, <i>J</i> .	/	
Printed Name: Robert Grybbs Jr.	1.1	proved by a	District Supervisor	Signe	1 Bv A	11/4 2	) KARPEU	1000
Title: Senior Environmental Coordinator	Ap	pproval DAUL 0 2 2013 Expiration Date:						
F '1.4.1)	1							
E-mail Address: rgrubbs@concho.com	- Co	Conditions of Approval:					1	
Date: 06-21-2013 Phone: 432-661-6601			······································					
Attach Additional Sheets If Necessary	R	Remediation per OCD Rule & 2RP-1693						

**Guidelines. SUBMIT REMEDIATION** PROPOSAL NO LATER THAN:

Remediation per OCD Rule &