

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 11 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC

Release Notification and Corrective Action

GW 1316839427 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 2169324	Contact: Gary Wink
Address: 2130 W Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL KEEL B #84	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001528551
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	05	17S	31E	2598	North	1293	East	Eddy

Latitude: 32.86356 Longitude: -103.88678

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 20 bbls/ 1 bbl	Volume Recovered: 0 / 0
Source of Release: 3" poly line- pin hole	Date and Hour of Occurrence: 06/03/2013 6am	Date and Hour of Discovery: 06/03/2013 6am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD	
By Whom? Gary Wink	Date and Hour 06/06/2013 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: while running route I noticed that there was a black spot out on pasture drove to location and found 3" poly line that was leaking and had a pin hole.

Describe Area Affected and Cleanup Action Taken.*: leak sprayed an area of 60x50, immediately put clamp on line to prevent it from leaking more . there was no fluid standing on ground, this leak occurred about 50 yards west of injection well #45, leak covered both north and south of lease road.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Gary W. Wink</i>	OIL CONSERVATION DIVISION	
Printed Name: Gary W. Wink	Approved by District Supervisor: Signed By: <i>M. Bratcher</i>	
Title: Production Foreman	JUN 17 2013 Approval Date:	Expiration Date:
E-mail Address: gawink@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/10/2013 Phone: 575-390-3477		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

July 17, 2013

2RP-1683