	UNITED STATE DEPARTMENT OF THE I BUREAU OF LAND MANA	OMB N Expires	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010				
SUNI	DRY NOTICES AND REPO	NOTICES AND REPORTS ON WELLS		5. Lease Serial No. NMLC049998A			
Do not u abandone	6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name					
SUBMIT II	N TRIPLICATE - Other instru	ctions on reverse side.	7. If Unit or CA/Agr	eement, Name and/or N			
1. Type of Well X Oil Well 🗖 Gas Well		8. Well Name and No. FOSTER EDDY 009					
2. Name of Operator COG OPERATING LLC.	9. API Well No. 30-015-26273						
3a. Address 600 W. ILLINOIS AVE. MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432-687-3033		10. Field and Pool, or Exploratory GRAYBURG JACKSON			
	Sec., T., R., M., or Survey Description		D 11. County or Parish	11. County or Parish, and State			
Sec 17 T17S R31E NWS	SE 2310FSL 1650FEL	JUL 09 201	3 EDDY COUNT	EDDY COUNTY, NM			
12. CHECK	APPROPRIATE BOX(ES) TO	O INDICAME PATHRE OF	SIA REPORT, OR OTHE	ER DATA			
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	AcidizeAlter Casing	 Deepen Fracture Treat 	Production (Start/Resume) Reclamation	□ Water Shut-C □ Well Integrity			
Subsequent Report	Casing Repair	□ New Construction	Recomplete	Other			
Final Abandonment Noti		☐ Plug and Abandon	 Temporarily Abandon Water Disposal 				
following completion of the in testing has been completed. Fi	\dots for a finite line $ i^{2} - \cdots$. ,			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ @ 1,255'-1,145'(B/SALT); WOO @ 920'-400' (8-5/8" CSG. SHC ⁻ . 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. I	TAG; CIRC. WELL W/ PXA CONTOC NMO X INSTALL DRY HOLE MARK SAST plug FIO	Dcele 7/9/1 cr record CD ER. M 557-			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ @ 1,255'-1,145'(B/SALT); WOO @ 920'-400' (8-5/8" CSG. SHC ⁻ . 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. I	X INSTALL DRY HOLE MARK	Dcele 7/9/1 cr record CD ER. M 357-			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ 2 1,255'-1,145'(B/SALT); WOO @ 920'-400' (8-5/8" CSG. SHO F. 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CS G G GO CS G GO	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. 7' 1 of 870, <u>Macker Reg.</u>	x INSTALL DRY HOLE MARK Spot plug fin SEE ATTACH CONDITIONS	Dicede 199/1 criteccord CD ER. M 357- ED FOR OF APPRON			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF MOTE; Surf 400 W OC	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 850'; PUMP 65 SXS. CMT. @ 1,255'-1,145'(B/SALT); WOO 0,20'_400' (8-5/8" CSG. SHO 5. 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CS 5 CMT. @ 500 Taylow Taylow CS 5 CMT. @ 500 Taylow Taylow CS 5 CMT. @ 500 Taylow Taylow CS 5 CMT. @ 500 Taylow	DEXT/SALT); WOCXTAG. DNSTEEL PLATE TO CSGS. 7' 10+ 870, <u>Macker Reg.</u>	x INSTALL DRY HOLE MARK Spot plug Fio SEE ATTACH CONDITIONS I Information System Arlsbad NS on 06(18/2013 () RECLAM	Dicedo 1 f 9/1 correccord CD ER. M 357- ED FOR OF APPRON ATION PROCEDUR			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF b)DIG OUT X CUT OFF Note; Surf 400 w oc	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ 2 1,255'-1,145'(B/SALT); WOO @ 920'-400' (8-5/8" CSG. SHO 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CSS & 30 7 	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. 7 107 870, <u>Macker Reg.</u> 210348 verified by the BLM Wel DEFRATING LLC., sent to the Ca	x INSTALL DRY HOLE MARK Spot plug fio SEE ATTACH <u>CONDITIONS</u> I Information System arlsbad NS on 06/18/2013 ()	Dcele 7/9/1 cr record CD ER. M 357-			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF 6)DIG OUT X CUT OFF Mote; Surf 4000 w oc <u>6 Ground Leve</u> 14. Thereby certify that the forego	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ 2 1,255'-1,145'(B/SALT); WOO @ 920'-400' (8-5/8" CSG. SHO 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CSS & 30 7 	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. 7 107 870, <u>Marker Reg.</u> 210348 verified by the BLM Wel DPERATING LLC., sent to the Ca for processing by KURT SIMMO	X INSTALL DRY HOLE MARK Spot plug fio SEE ATTACH CONDITIONS Information System arlsbad NS on 06/18/2013 () RECLAM	Dicedo 1 f 9/1 correccord CD ER. M 357- ED FOR OF APPRON ATION PROCEDUR			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF 6)DIG OUT X CUT OFF Mote; Surf 400 w oc <u>6 Cround Lewc</u> 14. Thereby certify that the forego	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ 2 1,255'-1,145'(B/SALT); WOO @ 920-400' (8-5/8" CSG. SHO - 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CS G G G CS G G C Electronic Submission # For COG O Committed to AFMSS f ID A EYLER ronic Submission)	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. 1 1 1 1 6 1 1 1 7 1 1 1 7 1 1 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	x INSTALL DRY HOLE MARK Spot plup fin SEE ATTACH CONDITIONS I Information System arlsbad NS on 06/18/2013 () D13	Dicelo 1 f 9/1 correccord CD ER. M 557- ED FOR OF APPRON ATION PROCEDUR			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF Mote; Surf 400 w oc <u>Commed Leve</u> 14. I hereby certify that the foreget Name(Printed/Typed) DAVI Signature (Electr	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ 1,255'-1,145'(B/SALT); WOO 9 920'-400' (8-5/8" CSG. SHO - 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CS G G GO I D G S G GO Committed to AFMSS f ID A EYLER ronic Submission) THIS SPACE FO	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. 7 1 0 7 870, Marker Reg. 210348 verified by the BLM Wel DERATING LLC., sent to the Ca for processing by KURT SIMMO Title AGENT Date 06/11/20	x INSTALL DRY HOLE MARK Spot plup fin SEE ATTACH CONDITIONS I Information System arlsbad NS on 06/18/2013 () D13	Decelo 19/1 cr record CD ER. M 357- ED FOR OF APPRON ATION PROCEDUR ATION PROCEDUR			
testing has been completed. Fi determined that the site is read 1)SQZ. 75 SXS. CMT. B 2)SET 5-1/2" CIBP. @ 2, MUD. 3)PUMP 25 SXS CMT. @ 4)PUMP 70 SXS. CMT. @ 4)PUMP 70 SXS. CMT. @ 5)MIX X CIRC. TO SURF 6)DIG OUT X CUT OFF Mote: Surf 400 W OC Contection Surf 400 W OC Contection Surf 14. I hereby certify that the forego Name(Printed/Typed) DAVI Signature (Electr Approved By Conditions of approval fif any, are a	y for final inspection.) ELOW A 5-1/2" PKR. @ 3,600 ,850'; PUMP 65 SXS. CMT. @ 2 1,255'-1,145'(B/SALT); WOO @ 920-400' (8-5/8" CSG. SHO - 15 SXS. CMT. @ 100'-3'. WELLHEAD 3' B.G.I; WELD C CS G G GO Committed to AFMSS f ID A EYLER ronic Submission) THIS SPACE FO MALL Approval of this notice does or equitable title to those rights in the	DE X T/SALT); WOC X TAG. DN STEEL PLATE TO CSGS. T 1 of 870, Macker Reg. P210348 verified by the BLM Wel DPERATING LIC., sent to the Ca for processing by KURT SIMMO Title AGENT Date 06/11/20 DR FEDERAL OR STATE O Title C	x INSTALL DRY HOLE MARK Spot plup fin SEE ATTACH CONDITIONS I Information System arlsbad NS on 06/18/2013 () D13	Dicedo 1/9/1 correcord CD ER. M 357- ED FOR OF APPRON ATION PROCEDIIR			

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Ution: U mpteited 1/ véy Cogs: Si unity: Er t and speed: 3: mit #: 3: vätton: 3: Calib: 11 perty Code: 11 vitton: 3: tory C	Location: 29137 Init J, SEC:17-T17S-R31E, 2310'FSL & 1650 /8/1991 DSN, LML ddy County, NM 20-305:100 @ 6 spm 708.5:GR 2 URRENTLY DOWN FOR TIGHT SPOT IN C ttemptied to work through tight spot @ 3661', 012).	ASING.			Spud Date: 1 Surf Csg: <u>B</u> Sot @ <u>1</u> Coment w/ <u>3</u>		507'
tion: U ipplētēð 1/ vēğ Logs: SI inty: Ec and spēed: 32 mit 4: Zation: 37 Calē: 11 perty: Code: iory C At 20 20 20 20 20 20 20 20 20 20	29137 Init J, SEC: 17-T17S-R31E, 2310'FSL & 1650 /8/1991 DSN, LML ddy County, NM 20-305:100 @ 6 spm 708.5 GR 2 2 <i>URRENTLY DOWN FOR TIGHT SPOT IN C</i> ttempted to work through tight spot @ 3661'	ASING.			API No: 3 Spud Date: 1 Surf Csg: 8 Set @ 1 Cement w/ 3	<u>1/29/1990.</u> -5/8, J-55 STC 24#, 2.jts:@ 070	507'
tion: U ipplētēð 1/ vēğ Logs: SI inty: Ec and spēed: 32 mit 4: Zation: 37 Calē: 11 perty: Code: iory C At 20 20 20 20 20 20 20 20 20 20	Init J, SEC: 17-T17S-R31E, 2310'FSL & 1850 /8/1991 DSN, LML ddy County, NM 20-305:100 @ 6 spm 708.5 GR 2 2 <i>URRENTLY DOWN FOR TIGHT SPOT IN C</i> ttempted to work through tight spot @ 3661".	ASING.			Spud Date: 1 Surf Csg: <u>B</u> Sot @ <u>1</u> Coment w/ <u>3</u>	<u>1/29/1990.</u> -5/8, J-55 STC 24#, 2.jts:@ 070	507'
ipiteited 1// rély Logis S. inity: Ec and speed: 37 mit#: 37 Valion: 37 Cale: 11 perty Code: 12 iory C 20 20	/8/1991 DSN, LML ddy County, NM 20-305:100 @ 6 spm 708.5 GR 2 2 <i>URRENTLY DOWN FOR TIGHT SPOT IN C</i> ttempted to work through tight spot @ 3661*	ASING.			Surf Csg: <u>B</u> Sot @ <u>1</u> Coment w/ <u>3</u>	-5/8, J-55 STC 24#,	507'
nty: Ex and speed: 32 mit #: Zaiton: 33 CaliC: 12 perty Code: 12 loory C At 20	ddy County, NM 20-305-100 @ 6 spm 708.5 GR 2 2 <i>URRENTLY DOWN FOR TIGHT SPOT IN C</i> ttempted to work through tight spot @ 3661*	ASING.			Set @ 1 Cement w/ 3	2 jts:@870	507'
and speed: 37 mit#: 37 CalC: 11 perty Code: 4 lony C A	20-305-100 @ 6 spm 708.5 GR 2 <i>URRENTL<u>Y DOWN FOR TIGHT SPOT IN C</u> Itempled to work through tight spot @ 3661'.</i>	ASING.			Set @ 1 Cement w/ 3	2 jts:@870	507'
nit #: Zalión: 33 Calê: 12 perty Code: 2 tory C Al	708.5 GR 2 CURRENTLY DOWN FOR TIGHT SPOT IN C ttempted to work through tight spot @ 3661".	ASING.			Cement w/ 3		501
Valion: 37 Calè: 11 perty Code: 2 tory C At 20	2 URRENTLY DOWN FOR TIGHT SPOT IN C ttempted to work through tight spot @ 3661"	ASING.				25 sxs Class C	1
perty Code: lory C At 20	URRENTLY DOWN FOR TIGHT SPOT IN C				circ. 3	5 sxs	
ory C Al 20	ttempted to work through tight spot @ 3661".						
ory C Ai 20	ttempted to work through tight spot @ 3661".						
FailurosN		Hung up on metal, s	shut down (Feb				
	ONE		م المراجع التي ا				
			· ·				
Directions.	• • • • • • • • • • • • • • • • • •		<u> </u>				
	Current			Z	N		
<u></u>	Tubing Detail (top to bottom)-				a de la constante de		
Joints:	Description	Footage	Depth		8		
			+	4 《新学校》			
	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·					
					8		
					Formations tops in		
			- terminenter	- 2000		2404'	
						2846' 3130'	
	<u> </u>				68 · · · · · · · · · · · · · · · · · · ·	4645	
					5X	4710	
		1	. The second second		Paddock		
	Rod Datall (top to bottom)				Blinebry		
Pumping Unit	320-305-100 @ 6 spm						
Rods .	Description	Footago	Depthy				
					ž.		
				- \$1223	8		
	· · · · · · · · · · · · · · · · · · ·				Grayburg: 2886-29	46' (Frac'd)	
4 1							
	ALEVAI		_ <u>L</u>		San Andros: 3239-	1317' (Frac'd)	
	NEW			_ % 833333	8		
	Tubing Detail (top to bottom)'	1			Light Boot in 5-1/2	and and a second second	
Joints	Description.	Footage			(IFob. 2012)	Casing from 3661-370	3 * -
79	2-7/8" J-55; 6:5# tbg; 8RD!"	- 2563.6	2,575.55*		(Feb.2012)		
<u></u>	2-7/8" Marker Joints J-55, 6.5# tbg, 8R 2-7/8" J-55, 6.5# tbg, 8RD	D	2:577.55				
2	2-7/8" J-55, 8:5# 15g, 8RD 2-7/8:X:541/2":Tubing Anchor.	64.9	2,642,45		Paddock: 3788-390	u, Hot Acidized	
	2-7/8" J-55, 6,5# lbg, 8RD		3,651.10		n a chuir an		
1	2-7/8"/SN	1.0	3,652.10		4743-5006', Acidiza	έi	
	4' - 2-7/8' Slotted Sub 2-7/8"BP	4.0	3,656,10, 3,656,60	4 2 00000	5160.4140 E		
	*		3,535.602		5158-5342', Frac'd		
			I		5338-5342', Acidiz	ed	
	D		····				
Pumping Unit:	Rod Detail (top to bottom) 320:305-100 ini:100" stroko		+				
Rods	Description	Footago	Depth		8		
.1	1-1/2" X'26' PR w/ 1-1/2" X 16' Liner,	. 26.0	26			1/2" 17# J-55 LTC	
-2	(2-4) 7/8" Pony subs		34.0:			27-its @ 5536', DV tool @	
140	7/8" Norris 90 rods	3350.0	3384.0		36	stg: 250 sxs class C; circ	
	.1-1/2" Sinker Bars: RHR tool	250.0			circ. <u>2</u> ,	stg: 2300 sxs class C, cir	c 150 sxs
1	2-7/8" Lift Sub	1.0	3635,0				
1	2-1/2" X 2" X 20' Trash (Quinn)	1.0	3652.0	PBTD: 5481	2		
				TD: <u>5560</u>			
a provincia de la composición de la composicinde la composición de la composición de la composición de	and and a second se						
cription		1bbis/ft		Burst PSI			
8" J-55; 6.5#	2.675" 2.441" 3.668"	0.00579 0.0325	0.2431	7000			
2" J-55, 17# 8" X 5-1/2"		0.0232 0.1305 0.0152 0.0886	0.9764 0.6625	4800			

3/4" Norris Steel 7/8" Norris Steel 1" Norris Steel 1-1/2" Polish Rod

r;

,

N90-97, 500t/lbs N90-97, 800t/lbs N90-97, 1200t/lbs 2800 ft/lbs .

COG Operating LLC. Foster Eddy #9 2310' FSL & 1650' FEL Sec. 17-T17S-R31E Eddy County, NM API: 30-015-26273 CIRC. 15 SXS. CMT, @ 100-3' T/Salt 450 Torsill 1324 Yatus 1482 SwarRives 1788 Qu 2404 GB 2846 PUMP 70 SXS. CMT @ 920-400'-TAG. PUMP 25 SXS. CMT, @ 1255-1145-TAG. SA 3130 GL 4650 Poddock 4908 PUMP 65 SXS. CMT. @ 2850-2350-TAG. GRAYTLENDH: 2100-2147 (FRACTO) AN ANDRES- 3230-3317 (FRACO). TICHT CHOT IN SILE CARRIE FROM SCOL STOP (FEB 2012) SOZ. 75 SXS CMT. @ 3600-TAG. PADDOCK: STES STOT. HOT ADDOZED 4743-5008 - ACIDIZED 5153-5342. FRACD SUIS STAT. ACCORED PBTD: 54B1 TD: 5560

۰.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

r

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11

2

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

з

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¹/₄ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ¹/₄ ¹/₄, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¹/₄ ¹/₄ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.bim.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Inspection & Enforcement

. .

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist 575-234-2230

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Doug Hoag Civil Engineering Technician 575-234-5979

Linda Denniston Environmental Protection Specialist 575-234-5974

Realty, Compliance

Randy Pair Environmental Protection Specialist 575-234-6240

Permitting

Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Tanner Nygren Natural Resource Specialist 575-234-5975

Amanda Lynch Natural Resource Specialist 575-234-5922

Leglon Brumley Environmental Protection Specialist 575-234-5957