
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103 Revised August 1, 2011	
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	WELL API NO.	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-24434	
District III – (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV - (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Johnson FE8. Well Number	
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	4	
2. Name of Operator Yates Petroleum Corporation	9. OGRID Number 025575	
3. Address of Operator	10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210	Eagle Creek; San Andres	
4. Well Location Unit Letter A : 990 feet from the North line and	990 feet from the East line	
Section 23 Township 17S Range 25E	NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, e 3481'GR	etc.)	
12. Check Appropriate Box to Indicate Nature of Notic	e, Report or Other Data	
	JBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PERF	ORK ALTERING CASING ORILLING OPNS. P AND A	
PULL OR ALTER CASING		
	П	
13. Describe proposed or completed operations. (Clearly state all pertinent details,		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of	
Yates Petroleum Corporation plans to plug and abandon this well as follows:		
 MIRU any safety equipment as needed. NU BOP. TOH with production equipment. RIH with bit and scraper to just below perfs at 1480' and circulate class "C" cement to 500' with 115 sx. NOTE: If fill is tagged and you are unable to get below the perfs then TOH and TBIH with CIBP and set above perfs at 1230' before circulating cement to 500' (90) 		
sx).	- · · · ·	
 3. Cut off wellhead and verify that there is cement behind all casing strings at surface. perforate and circulate cement to surface behind each casing string before cementing to 4. Install dry hole marker and clean location. 	surface inside production casing.	
4. Instanticity hole marker and clean location. CONDITION	S OF APPROVAL ATTACHED CEIVED	
Wellbore schematics attached Approval G		
NOTE: Yates Petroleum Corporation will use steel pits and no earth pits Completed		
	July 16, 2014 DARTESIA	
Spud Date: Rig Release Date:		
	Approved for plugging of well hore only. Histling under bond is retained pending receipt	
•	C 103 (Subsequent Report of Well Plugging)	
I hereby certify that the information above is true and complete to the best of my knowledge	edge and belieffin may be found at OCD web Fage under	
SIGNATURE ((June Lie Regulatory Reporting	g Supervisor DATE July 9, 2013	
Type or print name <u>Tina Huerta</u> E-mail address: <u>tinah@yatespetrol</u>	eum.com PHONE: <u>575-748-4168</u>	
BUNDO UN-TREMONDA 11 112		
APPROVED BY: /// Conditions of Approval (if any): A SEC AHAChow Mark	WIST (DATE Any 10, 200	
A JLE MANUL (UM)		

|

٦

1

Well Name:Johnson FE #4Field:Eagle CreekLocation:990' FNL & 990' FEL Sec 23-17S-25ECounty:EddyState:New MexicoGL:3,481'Zero:KB:Spud Date:3/30/1983Completion Date:4/20/1983Comments:API # 30015244340000



Casing Program	
Size/Wt/Grade	Depth Set
10 ¾ " 40.5# K-55	383'
7" 23# K-55	1,203'
4 ½" 9.5# K-55	1,494'
······································	

 Well Name:
 Johnson FE #4
 Field:
 Eagle Creek


 Location:
 990' FNL & 990' FEL Sec 23-17S-25E

 County:
 Eddy
 State:
 New Mexico

 GL:
 3,481'
 Zero:
 KB:

 Spud Date:
 3/30/1983
 Completion Date:
 4/20/1983

 Comments:
 API # 30015244340000
 API # 30015244340000
 API # 30015244340000



Casing Program	
Size/Wt/Grade	Depth Set
10 ¾" 40.5# K-55	383'
7" 23# K-55	1,203'
4 ½" 9.5# K-55	1,494'

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT
Operator: Votes Detro leum Corp.
Well Name & Numbers Johnson FE #4
API #: 30-015-24434

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE July 16, 2013

APPROVED BY: ROCOLO

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).