
Submit 1 Copy To Appropriate District	State of New Mex			Form C-103	
<u>District 1</u> – (575) 393-6161	Energy, Minerals and Natur	ral Resources	WELL API NO.	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-015-23172		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of L	ease	
<u>District III</u> (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE	FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	505	6. State Oil & Gas Le		
87505					
	ICES AND REPORTS ON WELLS		7. Lease Name or Un	it Agreement Name	
	OSALS TO DRILL OR TO DEEPEN OR PLU CATION FOR PERMIT" (FORM C-101) FO		Johnson FE		
PROPOSALS.)			8. Well Number		
1. Type of Well: Oil Well Gas Well Other			3		
2. Name of Operator			9. OGRID Number		
Yates Petroleum Corporation			025575 10. Pool name or Wildcat		
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210			Eagle Creek; San Andres		
4. Well Location			Lagic Creek, Sall Alle		
Unit Letter A :	330 feet from the North	line and	330 feet from the	East line	
Section 23	Township 17S Ran		NMPM Eddy	County	
	11. Elevation (Show whether DR,		···· · · · · · · · · · · · · · · · · ·	County	
	3470'				
12. Check	Appropriate Box to Indicate Na	ature of Notice.	Report or Other Da	ta	
			•		
	NTENTION TO:		SEQUENT REPO		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR					
		COMMENCE DRI		ND A	
		CASING/CEMEN	ГЈОВ 🗌		
DOWNHOLE COMMINGLE					
OTHER:		OTHER:			
	pleted operations. (Clearly state all p		d give pertinent dates, in	icluding estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or re	completion.				
Votos Detrolouro Como entico altro					
Yates Petroleum Corporation plans	to plug and abandon this well as follo	ows:			
1. MIRU any safety equipment as a	needed. NU BOP. TOH with produc	tion equipment.			
2. RIH with bit and scraper to just below perfs at 1480' and circulate class "C" cement to 500' with 115 sx. NOTE: If fill is tagged and					
you are unable to get below the perfs then TOH and TBIH with CIBP and set above perfs at 1230' before circulating cement to 500' (90					
sx).					
	there is cement behind all casing strin				
perforate and circulate cement to surface behind each casing string before cementing to surface inside production casing. 4. Install dry hole marker and clean location.					
4. Instan dry note marker and clear	location.	CONDITIONS O	F APPROVAL ATTACHE	D	
Wellbore schematics attached					
			nted providing work i		
NOTE: Yates Petroleum Corporati	on will use steel pits and no earth pit	s Completed by	11 110 20	14 1 0010	
	·····		July 10,00	1 2013	
Spud Date:	Rig Release Dat	e.	AIRAC		
			LAIAIC	CD ARIESIA	
			Approved for p	lugging of well bore only.	
I hereby certify that the information	above is true and complete to the bes	st of my knowledge	e and belief	bond is retained pending receipt	
· · · · · · · · · · · · · · · · · · ·	\wedge	·	which may be t	equent Report of Well Plugging) ound at OCD Web Page under	
			F	nrd.state.nm.us/ocd.	
SIGNATURE	TITLE Regul	latory Reporting Su	upervisor DATE Ju	<u>ily 9, 2013</u>	
Type or print name <u>Tina Hu</u>	erta E-mail address: tin	ah@yatespetroleun	n.com PHONE: _	575-748-4168	
For State Use Only					
APPROVED BY: NOW TITLE DIST ESperwish Date July 16 2013					
Conditions of Approval (if any):					
· · · · · · · · · · · · · · · · · · ·	SEE Attached	WHS		-	

•


. .

Well Name:Johnson FE #3Field:Eagle CreekLocation:330' FNL & 330' FEL Sec 23-17S-25ECounty:EddyState:New MexicoGL:3,470'Zero:KB:Spud Date:8/26/1981Completion Date:8/30/1981Comments:API # 30015231720000



Casing Program			
Size/Wt/Grade	Depth Set		
10 ¾" 32# K-55	295'		
7" 20# K-55	1,220'		
4½" 9.5# K-55	1,495'		

SKETCH NOT TO SCALE



7

.

DATE: 5/13/2013

Depth Set

295'

1,220'

1,495'

SKETCH NOT TO SCALE

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: 1/2tes Actroleum Coup Well Name & Number: Johnson FE #3 API #: 30-015-231

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.10. Plugs may be combined after consulting with and getting approval from NMOCD.11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: July 16, 2013

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).