

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED State of New Mexico  
Energy Minerals and Natural Resources  
AUG 23 2013 Oil Conservation Division  
1220 South St. Francis Dr.  
NMOCD ARTESIA Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nJM 1323850297 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company 14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs, NM, 88241	Telephone No. 575-602-2188
Facility Name: Quick Draw 10 G #1	Facility Type: Producing Oil Well

Surface Owner: S & JW Properties LLC	Mineral Owner: Steve Willard	API No: 30-015-36500
--------------------------------------	------------------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	10	20S	25E	2310'	North	1650'	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release: Oil Mist	Volume of Release: 10 bbls	Volume Recovered: 0 bbls
Source of Release: PRV Separator	Date and Hour of Occurrence 8-19-13	Date and Hour of Discovery 8-19-13
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Cause- Back pressure valve on separator malfunctioned causing pressure relief valve to open and spray mist across the North and Northeast side. Remedial Action- Backed off pressure on separator then dumped fluid from separator to water tanks.		
Describe Area Affected and Cleanup Action Taken.*		
Affected area- 200 ft to the North and 100 ft to the Northeast off the pad into the pasture. The pad was also affected around the separation equipment. Cleanup Action- Micro Blaze misted areas. Dig up and haul off contaminated caliche from pad then backfill with clean caliche.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <u>Zack Thomas</u>		OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas		Approved by Environmental Specialist: Signed By <u>Mike Brumley</u>	
Title: Environmental Rep.		Approval Date: <u>AUG 26 2013</u>	Expiration Date:
E-mail Address: zthomas@mewbourne.com		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>September 26, 2013</u>	Attached <input type="checkbox"/>
Date: 8-21-13	Phone: 575-602-2188		

\* Attach Additional Sheets If Necessary

2RP-1868