

RECEIVED

SEP 10 2013

NMOC D ARTESIA

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

1326033731

OPERATOR

Initial Report Final Report

Name of Company Oxy Permian	Contact C.J. Summers
Address 102 S. Main St. Carlsbad, NM 88220	Telephone No. 575-397-8216
Facility Name Riverbend Fed 8 SWD	Facility Type SWD

Surface Owner: BLM	Mineral Owner: Federal	API No. 30-015-28390
--------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 23	Township 24S	Range 29E	Feet from the 460	North/South Line North	Feet from the 330	East/West Line West	County: Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	--------------

Latitude 32.20900933 Longitude -103.962706393

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 60bbls	Volume Recovered 0
Source of Release Load out Line	Date and Hour of Occurrence: 7/12/13 11:20 am	Date and Hour of Discovery 7/12/13 11:20 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher of NMOCD Jim Amos & Jennifer VanCuren of BLM	
By Whom? C.J. Summers	Date and Hour July 15, 2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" steel load out line was pulled apart by a truck. 60bbls of fluid were released. All 60bbls were contained within the berms of the battery. Talon/LPE was contracted to perform an initial site assessment and soil sampling. Upon receipt of analytical results from the soil sampling activities, a work plan will be drafted and remedial activities will begin upon its approval.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within the berms of the battery. The tanks are elevated so the fluid was contained in the low spot between the elevated tank pad and the berms.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: C.J. Summers

Title: HES Advisor

E-mail Address: Chancey_Summers@oxy.com

Date: 9-9-13

Phone: 575-397-8216

Approved by Environmental Specialist:

Signed By: Mike Bratcher

Approval Date: SEP 17 2013

Expiration Date:

Conditions of Approval:

Attached

Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

Oct. 17, 2013

22P-1908

* Attach Additional Sheets If Necessary