Form 3160-5 (April 2004)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Artesia

FORM APPROVED

	Expires: March 31, 2
5.	Lease Serial No.

6. If Indian, Allottee or Tribe Name

NMLC050797

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well ☐ ☐ ☐ Gas Well ☐ ☐ ✓ Other					8. Well Name and No.		
2. Name of Operator Apollo Energ	Russell USA #049  9. API Well No.						
3a Address 120 W. Pujo St. Suite 300 Lake	Charles, LA 70601	3b. Phone No. (include area code) 337-502-5227		30-015-06186  10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  Section 13, T20S, R28E 660 FNL & 2000 FEL					Russell Field  11. County or Parish, State  Eddy County, New Mexico		
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, I	REPORT, OR	OTHER DATA		
TYPE OF SUBMISSION		TYI					
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Single Reclamation Recomplete Temporarily And Water Disposal	bandon	Water Shut-Off Well Integrity Other		
					ork and approximate duration thereof as of all pertinent markers and zones.		

- Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

  - 1. RIH with 2" pipe to bottom of casing
    2. Pump Class "C" Cement until full returns to surface
  - 3. POOH with 1" and wait 15 minutes and monitor well for fall back
  - 4. Top out well with cement
  - 5. Install 4" P & A marker per BLM requirements

RECLAMATION PROCEDURE ATTACHED

Tag Bottom of well bore, circulate cement to surface. At cut-off verify cement to surface on all annulus. If not take remedial action.

Audepted for record

SEP 3 0 2013 /s/ JD Whitlock Ji

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

## SEE ATTACHED FOR

CONL	<u>ЛП</u>	ONS OF APPROV	'AL	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Thomas G. Wright		Executive Vice President		RECEIVE
Signature Slohtfy		te 05/31/2013		OCT 2 2 2013
THIS SPACE FOR FEDERAL		NMOCD ARTE		
Approved by		Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.	[	Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter.	person within	knowingly and willfully to make to an its jurisdiction.	y department or age	ncy of the United

(Instructions on page 2)

