

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1330549623

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: 10" Water transfer mainline. The spill is located 155 ft. S.W. of the PLU-236 pumping well.	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-34419
------------------------	------------------------	----------------------


LOCATION OF RELEASE

Unit Letter H	Section 19	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-----------------

Latitude N 32.205853 Longitude W. 103.913044

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 30 bbls.	Volume Recovered: 0 bbls.
Source of Release: 10" Flange connection	Date and Hour of Occurrence: 10/29/13 time unknown	Date and Hour of Discovery: 10/29/13 at 2:20 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency response #104	
By Whom? Jody Walters	Date and Hour: 10/29/13 at 4:16 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		



Describe Cause of Problem and Remedial Action Taken.*
A flange on the 10" mainline developed a leak due to loose flange bolts, the bolts were re-torqued and the line was pressure tested.

Describe Area Affected and Cleanup Action Taken.*
Approximately 5,000 sq.ft. of pasture was affected by the release, all of the fluid soaked into the ground. The saturated soil around the spill area was excavated and stockpiled on-site pending disposal. The remediation will be in accordance to the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: Signed By <i>M. L. Benavides</i>	
Title: Waste Management and Remediation Specialist		Approval Date: NOV 01 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 10/31/13	Phone: 432-556-8730		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
December 1, 2013

2RP-2041