

1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources

Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
 accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**nJMW 1331839481**

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EnerVest Operating, L.L.C. 143/99	Contact	Bart Treviño
Address	1001 Fannin St., Suite 800	Telephone No.	713-659-3500
Facility Name	WLH G4S #55	Facility Type	Well Site/Tank Battery

Surface Owner	State	Mineral Owner		API No.	30-015-40525
---------------	-------	---------------	--	---------	--------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	02	18S	29E	1560'	South	80'	West	Eddy

Latitude 32.77349 Longitude -104.05372

#### NATURE OF RELEASE

Type of Release	Water & some crude oil	Volume of Release	8bbls total	Volume Recovered	8bbls
Source of Release	Flow line to tank battery	Date and Hour of Occurrence	11/7/13 @ approx. 7:30pm	Date and Hour of Discovery	11/7/13 @ approx. 7:30pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	Reubin Collins (EnerVest Foreman)	If YES, To Whom?	Randy Dade		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If a Watercourse was Impacted, Describe Fully.*					

**RECEIVED**

NOV 08 2013

**NMOCD-ARTESIA**

Describe Cause of Problem and Remedial Action Taken.\*

Driver of a water truck lost control of vehicle while trying to avoid livestock and busted the flowline to the battery. Driver contacted emergency contact on facility signage to notify EnerVest of the incident.

Describe Area Affected and Cleanup Action Taken.\*

Foreman spoke with Randy Dade about the incident and action to be taken. The release was between the well site and the tank battery. Will have Hydrovac to clean up/recover all fluids released. Further determination for soil will be made by NMOCD Inspector next week.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Bart Treviño	Approved by Environmental Specialist:	Signed By: <i>Mike Deaton</i>	
Title: Regulatory Analyst	Approval Date: NOV 14 2013	Expiration Date:	
E-mail Address: btrevino@enervest.net	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 11/8/13 Phone: 713-659-3500	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		

Attach Additional Sheets If Necessary

**December 14, 2013**

**2RP-2062**