Form 3160-5 (August 2007)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM111946

	SUN	DHY		ES AN	ID KEI	<b>2011</b> 5	ON W	ELLS	
Do	not L	ise this	s form	for pro	posals	to drill	or to r	e-enter a	ın
ha	ndoni	ed well	. Use	form 3	160-3 (/	APD) fo	r such	proposa	ıls

abandoned we	6. If In	If Indian, Allottee or Tribe Name     If Unit or CA/Agreement, Name and/or No.						
SUBMIT IN TRI	7. If Uı							
1. Type of Well		8. Well Name and No.						
🗖 Oil Well 🛛 Gas Well 🔲 Otl	TON	TOMBSTONE FEDERAL 1						
Name of Operator     COG OPERATING LLC	Contact: KANICI E-Mail: kcastillo@conchore	A CASTILLO esources.com	9. API Well No. 30-015-33869					
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	) W. ILLINOIS AVENUE Ph: 4	one No. (include area code) 32-685-4332		10. Field and Pool, or Exploratory CEMETARY MORROW				
4. Location of Well (Footage, Sec., T	r., R., M., or Survey Description)		11. Co	11. County or Parish, and State				
Sec 35 T19S R25E Mer NMP	EDI	EDDY COUNTY, NM						
12. CHECK APPI	ROPRIATE BOX(ES) TO INDIC	CATE NATURE OF N	OTICE, REPORT	OR OTHER	R DATA			
TYPE OF SUBMISSION	ACTION							
Notice of Intent	Acidize [	] Deepen	☐ Production (Star	t/Resume)	☐ Water Shut-Off			
■ Notice of Intent	☐ Alter Casing [	☐ Fracture Treat	☐ Reclamation		■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair [	☐ New Construction	☐ Recomplete		□ Other			
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon					
	☐ Convert to Injection	Plug Back	■ Water Disposal					
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  COG Operating LLC respectfully requests to recomplete to the Bone Spring and reclassify this well as an oil well.  Please see attached procedure.  1.) MIRU CU. Load hole. ND wellhead, NU BOP. TOH with tubing, laying down. 2.) Rig up wireline. RIH with CIBP and set at 9420??. Dump 35?? of cement on plug. 3.) Pick up and TIH with 2???? tubing to PBTD. Circulate hole with 3% KCI water. TOH. 4.) Perforate Bone Spring with 3???? casing guns, premium charges, 120⁰ phasing, 3 SPF in the following intervals: 6542??, 6562??, 6575??, 6589??, 6596??, 6603??, 6613??, 6624??, 6710??, 6720??, 6734??, 6740??, 6746??, 6755??  Provide CIOZ								
14. I hereby certify that the foregoing is	Electronic Submission #230014 v For COG OPERATI	ING LLC, sent to the Ca	ırisbad					
Name (Brings //Town B) - MANUOLA	Committed to AFMSS for process	* 1		()				
Name(Printed/Typed) KANICIA	CASTILLO	Title PREPA	HEH					
Signature (Electronic	Submission)	Date 12/18/20	013	ΛΟΩΟ	NVEN			
	THIS SPACE FOR FE	DERAL OR STATE	OFFICE USE	1411	OVLD			
Approved By  Conditions of approval, if any, are attached and the applicant holds lead or any	ed. Approval of this notice does not warr	Title ant or		FEB 3	1911/2 / A Sep			
certify that the applicant holds legal or eq which would entitle the applicant to cond	uct operations thereon.	Office		AU UF LANZ	MANAGEMENT			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime for statements or representations as to any m		willfully to make to any	departmentor-	agency-of-the-United			

# Additional data for EC transaction #230014 that would not fit on the form

### 32. Additional remarks, continued

Rig down wireline.
5.) TIH with tubing and tension packer. Set packer at 6500??. Swab well and report results.
6.) Rig up a pumping service company. Acidize interval with 3000 gallons of 15% HCl and 72 ball sealers at 5 BPM. Over displace 5 bbls.
7.) Swab back load.
8.) If shows warrant, move in pumping service company to frac the Bone Spring 9.) Flow back frac
10.) Install artificial lift.

Tombstone Federal 1 30-015-33860 COG Operating, LLC. January 28, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by April 28, 2014.

- 1. Operator shall place CIBP at 9,420' with 25sx Class H Cement on top to cover the top of the Morrow formation. Tag required at a minimum of 9,220' or shallower.
- 2. Must conduct a casing integrity test to max treating pressure before perforating and fracturing. Submit results to BLM. Notify BLM if test fails.
- 3. Prior to abandoning the Bone Spring formation the operator must submit an NOI to properly plug back the Wolfcamp formation, as it cannot be done at this time due to the proximity of Bone Spring perforations.
- 4. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 10. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 11. See attached for general requirements.

JAM 012814

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **General Requirements for Plug Backs**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.**
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.