Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103		
Office <u>District I</u> – (575) 393-6161	1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 OH. CONSEDVATION DIVISION			Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
811 S. First St., Artesia, NM 88210			30-015-40940 5. Indicate Type of	of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1000 Pio Brazos Pd. Aztes NM 97410			FEE	
<u>District IV</u> – (505) 476-3460	<u>st IV</u> – (505) 476-3460 Santa Fe, NWI 8/505		6. State Oil & Ga	s Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Tigger 9 State		
PROPOSALS.)			8. [Well (Nulmber)		
1. Type of Well: Oil Well Gas Well Other					
2. Name of Operator OXY USA WTP LIMITED PARTNERSHIP			9. OGRID Number 192463		
3. Address of Operator			10. Pool name or Wildcat		
PO BOX 4294; HOUSTON, TX 77210			GJ 7 RUS-QN-GB-	GLORIETA-YESO (97558)	
4. Well Location					
Unit LetterP:_420feet from theS line and _620feet from theEline					
Section 9	Township 17S Range		NMPM	County EDDY	
	11. Elevation (Show whether DR 35')		
		14			
. 12 Check A	nnronriate Box to Indicate N	Jature of Notice	Report or Other	Data	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
			SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORTEMPORARILY ABANDON CHANGE PLANS COMMENCE DR				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT				P AND A	
DOWNHOLE COMMINGLE		o, toll to, oeliver			
	_				
OTHER:	eted operations (Clearly state all		C/COMPLETIOIN	e including estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
4/2-/44					
1/25/14 – LOAD CASING WITH 2 BBL FRESH WATER PRESSURE UP ON CASING TO 5000 PSI, HOLD PRESSURE FOR 30					
MINUTES (GOOD)BLEED OFF PRESSURE, (STATE AND FEDERAL REGULATIONS REQUIRE PRESSURE TEST CASING AND RECORD RESULTS) WE PRESSURE TEST CASING TO 1500 PSI RUN A CHART FOR 30 MINUTES WITH A GOOD TEST.					
2/3/2014 - 2/8/2014 - 5192' - 5196', 5178' - 5180', 5159' - 5161', 5130' - 5132', 5119' - 5121', 5122' - 5127', 5114' - 5119',					
4992' - 5002', 4937' - 4942', 4792' - 4800', 4739' - 4743', 4631' - 4633', 4529' - 4531', 4502' - 4505', 4435' - 4438', 4356'					
- 4359', 4268' - 4276'; 4192' - 4196', 4122' - 4130', 4060' - 4066'; 3 SPF (350 holes); 0.48" EHD. Fluid - 1,320,186gals					
water; 99,918 gals 12# linear gel; 188,496 12# crosslink gel; 13,000 gals 15% HCl. Sand - 183,780 lbs 40/70 brown sand;					
191,860 lbs 30/50 brown sand; 357,700 lbs 16/30 brown SD					
<u>2/10/2014</u> – MIRU CLEANOUT RIG. BEGIN AFTER FRAC CLEANOUT.					
<u>2/13/2014</u> – COMPLETE AFTER FRAC CLEANOUT TO PBTD. <u>2/14/2014</u> – 2/17/2014 – Run 2-7/8" J-55 tbg to 5249'. Run production equipment.					
<u>2/14/2014 - 2/17/2014</u> – Run 2-7/8" J	-55 tbg to 5249'. Run production	equipment.	i HEC	JEIVED	
			 	7 2014	
Spud Date:	Rig Release D	eate:	į		
			MNOC	DARTESIA	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
Amarika hila a N					
SIGNATURE / / / DATE _03/06/2014					
Type or print normal IEMNIFEE DIL	ADTE E mail addresses	ionnifa d	DUON	É. 712 512 6640	
Type or print name _JENNIFER DUARTE E-mail address: _jennifer_duarte@oxy.com PHONE: _713-513-6640 For State Use Only					
APPROVED BY: TITLE 157 TO DATE 3 11 2014 Conditions of Approval (if any):					
Conditions of Approval (if any):		,		·	